## 9.2 AMENDMENT TO THE MUNICIPAL HERITAGE INVENTORY - NO. 40 GUILDFORD ROAD, MOUNT LAWLEY

#### Attachments:

- 1. Applicants Report
- 2. Main Roads Approved Land Dealings Plan Guildford Road and East Parade
- 3. Heritage Impact Statement
- 4. Proposed Demolition of Heritage Listed Single House Photographic Archival Record
- 5. Department of Planning, Lands and Heritage Letter of Response to City of Vincent Council Resolution Removal of No. 40 Guildford Road from Municipal Heritage Inventory
- 6. Main Roads Western Australia Traffic Assessment Report

#### **RECOMMENDATION:**

#### **That Council:**

- 1. RESOLVES that No. 40 (Lots: 254 and 403) Guildford Road, Mount Lawley be removed from the City's Municipal Heritage Inventory pursuant to Schedule 2, Part 3, Clause 8(3)(d) of the *Planning and Development (Local Planning Schemes) Regulations 2015*; and
- 2. NOTES that Administration will notify the Heritage Council of Western Australia and the owner of the place of this decision pursuant to Schedule 2, Part 3, Clause 8(4) of the *Planning and Development (Local Planning Schemes) Regulations 2015.*

#### **PURPOSE OF REPORT:**

For Council to consider a request to remove No. 40 Guildford Road, Mount Lawley (the subject site), from the City's Municipal Heritage Inventory (MHI).

The applicant is seeking to remove the subject site from the MHI to enable a house on the property to be demolished. This is to facilitate the comprehensive development of the wider Mount Lawley Housing Diversity Pipeline site and to accommodate road widening requirements for the planned upgrade of the Guildford Road/East Parade Intersection.

This item was previously deferred by Council at its Ordinary Meeting on 17 October 2023 to enable additional information to be provided.

Additional information has been submitted by the applicant and is the subject of this report.

#### **DELEGATION:**

This item is being referred to Council for determination in accordance with the City's Register of Delegations, Authorisations and Appointments. This is because Council is required to determine any requests to remove a place from the MHI.

#### **BACKGROUND:**

#### Site Context

The subject site is zoned Residential R100 under the City's Local Planning Scheme No. 2, is located within the Transit Corridor Built Form Area and has a building height limit of three storeys under Policy No. 7.1.1 – Built Form.

The subject site contains a single-storey brick and corrugated zincalume residence designed in the Federation Queen Anne style and was constructed circa 1904.

#### Heritage Status

The subject site was added to the City's MHI in 2000 and is currently listed as a Management Category B – Conservation Recommended.

In August 2007 a request was received from Main Roads Western Australia (MRWA) for the demolition of the house on the subject site. The City conducted a review at the time and determined the subject site met the threshold for its retention on the MHI. As part of this review, the following Statement of Significance was prepared:

'The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity.'

At its meeting on <u>4 December 2007</u> Council resolved to retain the subject property as Management Category B - Conservation Recommended on the MHI. This listing affords the property statutory protection as a heritage listed place.

#### **Current Property Condition**

The subject property has been vacant for a number of years and is currently in a derelict state both internally and externally. The historic fabric of the property has been significantly reduced through vandalism and general deterioration as shown in **Figures 1 and 2** below.



Figure 1: Street Elevation



Figure 2: Rear Elevation

#### **Guildford Road Reservation**

The subject site abuts Guildford Road, which is reserved as a Primary Regional Road (PRR) under the Metropolitan Region Scheme (MRS). MRWA is responsible for the control and management of PRR's.

MRWA has additional land requirements beyond the existing PRR reserve which will impact the subject site. This is shown in **Figures 3 and 4** below.



Figures 3 and 4: Primary Regional Road Reservation - Ultimate Land Requirements

The applicant has advised that the final MRS reservation reflecting these additional land requirements will be gazetted through an omnibus amendment following construction of the road upgrades. Neither the DPLH or MRWA have provided a timeline for commencement of the road upgrades.

The applicant has also advised that to ensure the land is protected, the DPLH have agreed with MRWA for the required road widening to be excised and set aside through a plan of subdivision which is currently being prepared for lodgement with the WAPC.

The subject site is currently fenced off as to allow for remediation works and wider site preparation to occur in relation to the State Government's Housing Diversity Pipeline Project. Further information on the project timeline can be found below.

#### Housing Diversity Pipeline Project

The subject site forms part of a wider government landholding comprising of 34 lots (including the subject site) situated along Guildford Road and East Parade. A plan showing these 34 lots is included within the applicant's report (**Attachment 1**).

These lots have been identified for the delivery of social housing as part of the State Government <u>Housing Diversity Pipeline (HDP) program</u>. The form and scale of the future development has not yet been determined.

This project will enable the renewal of vacant land along Guildford Road and East Parade and provide for additional social and affordable housing.

DPLH officers have advised Administration that the announcement of the successful proponent and wider subdivision of the site is expected in the second half of 2024.

#### Council Deferral October 2023

In July 2023 the City received an application from Element acting on behalf of the DPLH for the removal of the subject site from the City's MHI. The applicant's supporting report for the proposal is included as **Attachment 1**.

The DPLH is proposing the demolition of the dwelling on the subject site to cater for future widening of Guildford Road as well as to achieve the aims of the HDP program. The widening of Guildford Road is shown in **Attachment 2**. This will not be in effect until the MRS is amended to widen the PRR reserve.

In support of the application, the applicant has provided a Heritage Impact Statement (**Attachment 3**), and a Photographic Archival Record (**Attachment 4**).

Council considered the proposal at its <u>meeting on 17 October 2023</u> and resolved to defer its consideration for the following reason:

'That the motion be deferred to seek further advice from the Department of Planning, Lands and Heritage and Main Roads WA regarding the justification for widening in this particular location, supported by traffic studies, applicable standards and potentially requesting some level of detailed design around what is proposed in this area that would necessitate demolition of this structure.

An updated report is to be provided to Council by March 2024'.

The DPLH provided additional information on 1 March 2024 in response to Council's deferral reasons. This additional information includes a Letter of Response (**Attachment 5**) and Traffic Assessment Report (TAR, **Attachment 6**).

The additional information did not include a detailed design of the proposed road works. Because of this the ultimate land requirements as detailed in the approved land dealings plan in **Attachment 2** remains the most accurate plan currently available which delineates the extent of road widening.

#### Assessment in Previous Administration Report

The <u>previous report</u> that was considered by Council at its Ordinary Meeting on 7 October 2023 included Administration's comments on the assessment of the proposal against:

- Local Planning Policy No. 7.6.2 Heritage Management Assessment (LPP 7.6.2);
- Local Planning Policy No. 7.6.5 Heritage Management Amendments to the Municipal Heritage Inventory (MHI) (LPP 7.6.5); and
- The Heritage Council of Western Australia (HCWA) Guidelines for the Assessment of Local Heritage Places.

The additional information provided following Council's deferral has not impacted the previous assessment of the proposal against these policies, and these assessment comments remains applicable.

#### Assessment of Additional Information Submitted

An assessment of the additional information provided in response to Council's deferral reasons is set out below

#### Traffic Assessment Report

The DPLH provided a TAR which was prepared by MRWA. This report includes a comparison of the existing Guildford Road to East Parade single left turn pocket against the proposed dual left turn pocket.

The proposed dual left turn pocket would be within the PRR widening area and would be controlled by traffic signals as part of the ultimate upgrade.

This comparison is shown as Option 2a in the TAR in Attachment 6 as well as Figure 5 below.




Figure 5: Proposed Guildford Road/East Parade road upgrades. Future extension subject to this report highlighted in red.

The two approaches were assessed based on the Degree of Saturation (DOS), Level of Service (LOS) and critical queue length:

- The DOS is a measure of the capacity of an intersection. A DOS greater than 100 percent indicates the intersection is over capacity. The TAR states that the desired DOS for a signalised intersection such as Guildford Road and East Parade is 90 percent.
- The LOS indicates the average delay that a vehicle would experience at an intersection. There are six LOS grades ranging from A (Good) to F (Poor). The TAR states that generally a LOS of 'D' or better is desired.
- The critical queue length indicates the extent of the backlog (in metres) caused by delayed vehicles. It helps assess whether the queued traffic in a turning pocket would encroach into the through lane.

The TAR findings are summarised below.

 <u>Current Intersection Design</u> – The TAR indicates that the current intersection would operate poorly in 2026 and would exceed the desirable DOS and LOS. This would result in impacts to the flow and safety of traffic.

The AM peak period would experience a DOS of 118 percent and an LOS of 'F'. This would result in 80 vehicles queuing with a delay of over two minutes to turn left onto East Parade. The vehicle queuing would extend beyond the pocket length of 145 metres to approximately 600 metres.

The PM peak period would experience a DOS of 85 percent and a LOS of 'E'. This would result in 41 vehicles queuing with a delay of over one minute to turn left onto East Parade. The vehicle queuing would extend to approximately 300 metres.

The vehicles that are unable to be contained in the pocket would pose a safety risk because of the higher likelihood of being involved in a rear-ended crash with the through movement vehicles.

 <u>Proposed Intersection Design</u> – The TAR indicates that the performance intersection would improve to be within the desired levels with the implementation of dual left turn pockets compared to the current intersection design in 2026. This would result in improved traffic flow and safety.

In 2031 these upgrades would be expected to result in the intersection experiencing a DOS of 63 percent and 28 percent, and a LOS of 'C' and 'B', in the respective AM and PM peak periods. This would result in 22 vehicles and seven vehicles queuing at the intersection in the AM and PM peak periods, with a maximum delay of 20 seconds. The maximum queue length would reduce to 50 metres in the AM peak and 159 metres in the PM period.

Similar improvements are anticipated to remain in 2036. These upgrades would be expected to result in the intersection experiencing a DOS of 65 percent and 29 percent, and a LOS of 'C' and 'B', in the respective AM and PM peak periods. This would result in 25 vehicles and eight vehicles queuing at the intersection in the AM and PM peak periods, with a maximum delay of 28 seconds. The maximum queue length would increase to 185 metres in AM peak and 58 metres PM peak periods.

The proposed left turn pocket length would account for the projected traffic queue, ensuring left-turning vehicles are not held up in the through queue and impact on the efficient flow of traffic through this intersection.

<u>Conclusion</u> – The additional road widening area beyond the existing PRR which impacts the subject site
would be necessary to upgrade the Guildford Road/East Parade intersection. This is to improve traffic
flow by ensuring that vehicles are not held up in the through lane, improving the overall safety of the
intersection by reducing the vehicle backload which would encroach in the through lane.

The TAR has been reviewed by the City's traffic engineers, is acceptable and findings are supported.

From a traffic flow and safety perspective, the 2026 modelling under the current intersection design shows traffic queues having negative impacts to the intersections of Guildford Road with Ellesmere Street and Stanley Street within the City of Bayswater.

This would adversely impact on existing residential areas that are accessed by Guildford Road, as well as local bus services along Guildford Road and East Parade/Whatley Crescent.

The proposed widening to facilitate the implementation of dual left-turn pockets would minimise the operation and flow of the intersection to be within its capacity and result in improved safety and accessibility outcomes for all road users.

#### Detailed Design

The DPLH has advised that the intersection upgrade is yet to progress through the project development phase which includes development of detailed road designs and road sections. A timeframe has not been provided for this stage.

As part of progressing the project development phase, MRWA would undertake further consultation with the City to resolve the detailed designs.

The approved land dealings plan included in **Attachment 2** is the most accurate plan currently available which delineates the extent of road widening required to accommodate the current intersection upgrade design based on the preferred design scenarios tested in the TAR.

#### Estimated Timelines for the Project

Should Council resolve to approve the removal of the subject property from MHI, officers from the DPLH have advised Administration that the MRS amendment to widen the existing Guildford Road reservation in line with the approved land dealings plan included in **Attachment 2** would be submitted in the second quarter of 2024.

DPLH officers have also advised that it is anticipated that the State Government will make an announcement of the preferred proponent for the Mount Lawley HDP project in the second half of 2024, with the development application to be lodged after this.

#### **CONSULTATION/ADVERTISING:**

Community consultation for the proposal was undertaken from 28 July to 18 August 2023 in accordance with Community and Stakeholder Engagement Policy and included the following:

- Advertisement placed in the Perth Voice newspaper;
- A sign placed on site;
- Notice displayed on Imagine Vincent website;
- Letters were sent to adjoining and adjacent neighbours in accordance with the Community and Stakeholder and Engagement Policy; and
- A referral being sent to the heritage division of the DPLH.

Seven submissions were received from the community, including three in support of the property's removal from the MHI and four objecting. A summary of the submissions received and Administration's response can be found in the <a href="https://doi.org/10.1007/journal

#### Notification to Previous Submitters

The additional information provided in response to Council's deferral reason was not readvertised to the community. This is because it does not result in a significantly different proposal to that which was previously advertised.

Correspondence to the previous submitters has been provided notifying them of the additional information provided in support of the proposal and on the meeting dates of Council.

At the time of preparing this report Administration had not received any further comments from the previous submitters.

#### **LEGAL/POLICY:**

- Heritage Act 2018;
- Planning and Development (Local Planning Schemes) Regulations 2015;
- City of Vincent Local Planning Scheme No. 2;
- Local Planning Policy No. 7.6.2 Heritage Management Assessment;
- Local Planning Policy 7.6.4 Heritage Management Interpretation; and
- Local Planning Policy No. 7.6.5 Heritage Management Amendments to the Municipal Heritage Inventory.

#### **RISK MANAGEMENT IMPLICATIONS**

Low: It is low risk for Council to remove the subject site from the MHI as the removal of a place from the MHI. This is because LPP 7.6.5 provides guidance on the removal of a place from the MHI.

The removal of subject site from the MHI forms part of the State Government's HDP project to widen the existing PRR area and facilitate the redevelopment of the 34 properties fronting Guildford Road and East Parade to provide for social and affordable housing.

Should Council resolve to retain the subject site on the MHI, it is anticipated that the State Government through the DPLH would explore all options to pursue its removal and progress the HDP project.

#### State Administrative Tribunal (SAT) Review

Council's decision in respect to a request for a property to be removed from the MHI is not a decision that is reviewable.

In June 2023 the applicant on behalf of the DPLH submitted a development application (DA) to the City that proposed the demolition of the existing dwelling on the subject site.

The applicant and the City agreed to an extension of time for processing the DA, This would allow the progress of a request for removal of the subject site from the MHI in the interest of orderly and proper planning. A DA would no longer be required if the site was removed from the MHI and only a building permit would be required for the demolition works. This means that the DA could be cancelled.

Should Council not support the removal of the property from the MHI, the applicant could seek a decision from Council on the DA. If the DA was to be refused, the applicant would have the option of seeking a review of the decision through SAT.

The DA was placed on hold at 60 days with the agreement of the applicant while the removal of the property from the MHI is considered by Council. Should Council not make a determination on the DA within the statutory timeframe of 90 days, the applicant has the option of seeking a review through SAT as a deemed refusal.

Should the matter be pursued at the SAT there would be a resource and financial implication to the City.

#### Reputational Risk

There would be a potential reputational risk to Council in being to perceived to be:

- Inhibiting the safe and efficient movement of vehicles on the road network by delaying MRWA attempts to upgrade the Guildford Road/East Parade intersection.
- Inhibiting the progress of the State Government's HDP project given the current housing shortage being experienced within wider Perth.

#### STRATEGIC IMPLICATIONS:

This is in keeping with the City's Strategic Community Plan 2022-2032:

#### Connected and Healthy Community

We are an inclusive, accessible and equitable City for all.

#### **Thriving Places**

We encourage innovation in business, social enterprise and imaginative uses of space, both public and private.

#### Sensitive Design

Our planning framework supports quality design, sustainable urban built form and is responsive to our community and local context.

#### **Innovative and Accountable**

We engage with our community so they are involved in what we are doing and how we are meeting our goals.

#### FINANCIAL/BUDGET IMPLICATIONS:

There are no budget implications to remove the place from the MHI.

Should Council resolve to maintain the subject site on the MHI, the City may incur costs related to engaging consultants and legal representatives in SAT, and depending on the outcome of the DA.

This would be met through the existing Operational Budget.

#### **COMMENTS:**

The dwelling's current degraded state has been caused through neglect and the dwelling could be restored without impacting its significance.

Notwithstanding this, Administration recommends that Council remove the subject site from the MHI because:

 Heritage Impact – The removal of the property from the MHI would be consistent with LPP 7.6.5 and is supported.

The property is currently in a poor condition as shown in **Figures 1 and 2**. Administration is of the opinion that this degraded state has been caused through neglect and that the dwelling could be restored without impacting its significance.

However, the widening of the Guildford Road PRR is a relevant consideration because this would necessitate either complete demolition, or partial demolition and substantial modification of the existing dwelling.

The extent of demolition and/or modification would have a material impact on the fabric of the existing dwelling such that the original character, authenticity and significance of the dwelling would be irreversibly impacted and could not practically be retained. Further analysis can be found in Administration's report to Council on 17 October 2023.

• Road Upgrades & Safety – The TAR has demonstrated that the current road network would operate beyond its capacity in 2026 and have a negative impact on traffic movement and safety.

The proposed road widening would facilitate upgrades to the Guildford Road and East Parade intersection, as shown in **Attachment 2** and **Figure 5**.

These upgrades would be necessary to alleviate existing issues at this intersection and to ensure the safe and efficient movement of private vehicles and public transport on the regional road network.

If determined by Council consistent with the officer recommendation, Administration will notify the HCWA and the owner of the place of this decision pursuant to Schedule 2, Part 3, Clause 8(4) of the *Planning and Development (Local Planning Schemes) Regulations 2015.* Administration will also notify those who made a submission.

# element.

Our Ref: 23-212

5 September 2023

Chief Executive Officer
City of Vincent
244 Vincent Street
LEEDERVILLE WA 6902

Attention: Karsen Reynolds - Coordinator Planning Services

Dear Karsen,

# PROPOSED DEMOLITION OF EXISTING HERITAGE LISTED SINGLE DWELLING – LOTS 254 & 403 (NO. 40) GUILDFORD ROAD, MOUNT LAWLEY

element acts on behalf of the Department of Planning, Lands and Heritage ('DPLH') in relation to the above matter. Please find enclosed an Application for Development Approval for the demolition of the existing residential dwelling situated on Lots 254 & 493 (No. 40) Guildford Road, Mount Lawley (the 'subject site').

In accordance with the City of Vincent's requirements, please find enclosed:

- A completed and signed City of Vincent Application for Development Approval form;
- A completed and signed MRS Form 1;
- A current copy of the Certificate of Title for the subject site;
- A copy of the proposed demolition plan; and
- Supporting justification contained within this correspondence.

#### 1.0 SITE DETAILS

The subject site comprises two (2) lots, legally defined as set out in Table 1 below.

Table 1 - Certificate of Title Details

Lot	Plan	Vol	Folio	Street Address	Land Area	Registered Proprietor
403	31182	2209	507	40 Guildford Road, Mt Lawley	312m²	WA Planning Commission
254	2001	2209	507	40 Guildford Road, Mt Lawley	417m²	WA Planning Commission

Refer Attachment One - Certificate of Title.

The subject site forms part of a wider government landholding comprised of 34 lots situated along Guildford Road and East Parade (Attachment Two) which have been identified for the delivery of social housing as part of the Housing Diversity Pipeline.

#### 2.0 BACKGROUND - THE HOUSING DIVERSITY PIPELINE

The Housing Diversity Pipeline (HDP) is part of the State Government's commitment to improve the quality and accessibility of social housing in Western Australia. Several agencies including DPLH) are working collaboratively to identify and offer suitable surplus Government-land to the market for innovative housing developments that provide for social housing and deliver more housing choice for our communities.

Project delivery methods may include (but are not limited to) long-term ground leases, partnership models, and design and construct models for either build-to-rent or build-to-sell housing. All developments must deliver a minimum of 20 per cent of social housing dwellings across the development.

The broader landholding (herein referred to as the "Mount Lawley HDP site") of which the subject site forms a part was one of nine sites released to market through an Expression of Interest (EOI) process in August 2022. The EOI process has been completed and the shortlist of respondents to progress to the next phase of procurement has been approved and successful proponents have been informed.

The Mount Lawley HDP site received submissions that were shortlisted. The next stage will involve a request for detailed proposals where multiple suitable proponents have been shortlisted, or a direct negotiation process where only one proponent has been shortlisted. The Mount Lawley HDP site received submissions that were deemed to meet the State Government's social housing objectives and will proceed to this stage.

#### 3.0 PROPOSED DEMOLITION

This Development Application proposes the full demolition of the existing residential dwelling and all associated infrastructure at the subject site to facilitate comprehensive re-development of the wider Mount Lawley HDP site.

For reasons that will be detailed in this submission, full demolition of the existing residential dwelling is proposed (i) for the purpose of improving housing choices and access to suitable and affordable homes – particularly for the most vulnerable, and (ii) to accommodate road widening required for the delivery of major road upgrades at the Guildford Road / East Parade intersection.

The form and scale of the development has not been determined at this stage and will be subject to detailed design development as part of the next stage of the procurement process.

#### 4.0 ZONING AND RESERVATIONS

#### **Metropolitan Region Scheme**

The Metropolitan Region Scheme ('MRS') is the overriding statutory land use planning scheme for the Perth Metropolitan Region and provides the legal basis for the applicable development control and use of land at the regional level.

Under the provisions of the MRS, the subject site is zoned 'Urban' (Figure 1).

#### Road Widening Requirement

The subject site abuts Guildford Road, which is reserved for 'Primary Regional Roads' (PRR) under the MRS (Figure 1).


The subject lot was originally acquired by the State along with all other properties fronting Guildford Road between Stanley Street and Packenham Street in 1997 to allow for upgrades to Guildford Road and East Parade. Between 2000 and 2001 minor upgrades were complete for the addition of a turning lane on Guildford Road.

Land has previously been excised from the subject lot and set aside for road reserve abutting Guildford Road in preparation of future major capacity upgrades at the intersection of Guildford Road and East Parade. The current MRS reservation delineates additional land requirements for a number of lots along Guildford Road over and above the land which has previously been excised (Figure 1).



Figure 1 - Metropolitan Region Scheme

Main Roads WA (MRWA) has developed plans for the proposed ultimate upgrades at the Guildford Road / East Parade intersection and has issued an ultimate land take requirement plan for the required road widening which shows land requirements affecting the subject lot beyond the current extent of the PRR and beyond that of the land previously excised (Figure 2).






Figure 2 - Primary Regional Road - Ultimate Land Requirements

MRWA have advised that an MRS amendment to reserve the land as PRR will not be progressed prior to delivery of the road upgrades as there is no immediate need to protect the required land via a statutory mechanism due to the fact that the State is currently the sole landowner for all affected land. It is standard practice that the final MRS reservation will be gazetted through an omnibus amendment following construction of the road upgrades.

To ensure the land is protected, DPLH have agreed with MRWA for the required road widening to be excised and set aside through a plan of subdivision which is currently being prepared for lodgement with WAPC. A deposited Plan has been prepared for the subdivision showing the amalgamation of 34 lots abutting Guildford Road and East Parade between Stanley Street and Gardiner Street to create 4 balance lots for future redevelopment and set aside land for road widening. The extent of land proposed to be set aside for road widening is consistent with the current land take requirements plan issued by MRWA.

Refer Attachment Three - Draft Deposited Plan

#### Road Widening Impact

The planned road widening affecting the subject lot will necessitate modification of the existing dwelling to eliminate any encroachment into the future road reserve. The primary frontage of the dwelling including the front room, steps, verandah and associated footings will be an encroachment in the road reserve and require partial demolition and substantial modification.

The extent of these required modifications will have a material impact on the fabric of the existing dwelling such that it is considered the original character of the dwelling will be detrimentally impacted and cannot practically be retained. Figure 4 shows an overlay of the endorsed road widening requirements in relation to the surveyed location of the dwelling, highlighting the affected areas.






Figure 3 - MRWA Road Widening Overlay

#### City of Vincent Local Planning Scheme No. 2

The City of Vincent Local Planning Scheme No. 2 ('LPS 2') sets out the provisions for development control and land use within the City. Pursuant to the provisions of LPS 2, the subject site 'Residential' and has an applicable density coding of 'R100' as contemplated under the Residential Design Codes of WA (the 'R-Codes').

The objectives of the Residential zone as contemplated under LPS 2 are detailed below:

- To provide for a range of housing and a choice of residential densities to meet the needs of the community;
- To facilitate and encourage high quality design, built form and streetscapes throughout residential areas:
- To provide for a range of non-residential uses, which are compatible with and complementary to residential development;
- To promote and encourage design that incorporates sustainability principles, including but not limited to solar passive design, energy efficiency, water conservation, waste management and recycling:
- To enhance the amenity and character of the residential neighbourhood by encouraging the retention of existing housing stock and ensuring new development is compatible within these established areas;
- To manage residential development in a way that recognises the needs of innovative design and contemporary lifestyles;
- To ensure the provision of a wide range of different types of residential accommodation, including affordable, social and special needs, to meet the diverse needs of the community.

Lots 254 and 403 form part of an overall WAPC landholding comprising 34 lots (Mount Lawley HDP site), forming an area of approximately 13,638m<sup>2</sup> located alongside East Parade and Guildford Road, as detailed in the Figure 4 below.

The proposed demolition will facilitate the future development of the landholding, contributing significantly to housing choice and affordability in a key location in proximity to public transport and amenities.

Development of the land holdings which are predominately vacant will enhance amenity in the locality by activating an underutilised area and improve safety through removal of the existing dwelling at the subject site which is currently derelict.



Figure 4 - Landholding for Future Development

#### 5.0 HERITAGE CONSIDERATIONS

#### **City of Vincent Municipal Heritage Inventory**

The City's Municipal Heritage Inventory ('MHI') lists the existing dwelling at the subject site as a 'Moderate Level of Significance' which is described as:

Contributes to the heritage of the locality. Has some altered or modified elements, not necessarily detracting from the overall significance of the place.

Management Category B - Conservation Recommended

Consider for inclusion on the MHI (Heritage List) if owner/applicant consents to inclusion.

The City of Vincent prepared the following statement in 2006 with regard to the dwelling:

The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity.

The dwelling is in a state of disrepair and currently boarded up. Graffiti is evident internally and externally.



#### City of Vincent Heritage Management Local Planning Policies

#### Local Planning Policy 7.6.1: Heritage Management – Development Guidelines

The City's 'Local Planning Policy 7.6.1: Heritage Management – Development Guidelines for Heritage and Adjacent Properties' ('LPP 7.6.1') seeks to assist owners in undertaking alterations and additions to places listed on the City's MHI.

LPP 7.6.1 notes that planning approval from the City is required where demolition of a heritage place is proposed. Consistent with the requirements of the policy, this application seeks approval from the City for demolition of the existing dwelling at the subject site to facilitate the future development of social housing.

#### Local Planning Policy 7.6.4: Heritage Management – Interpretive Signage

As contemplated under the City's 'LPP 7.6.4 – Heritage Management – Interpretive Signage' ('LPP 7.6.4'), we understand that the City may require Interpretive Signage to recognise the history of the place as a condition of the approval. However, given a photographic archival record of the dwelling has been undertaken, this is considered adequate in terms of capturing the historical record of the site. No interpretation signage is considered necessary as part of the demolition and future redevelopment of the site.

# <u>Local Planning Policy 7.6.5: Heritage Management – Amendments to the Municipal Heritage Inventory</u>

The City's 'LPP 7.6.5: Heritage Management – Amendments to the Municipal Heritage Inventory' ('LPP 7.6.5') outlines that the City may consider amendments to the MHI through the Demolition Planning Application process. LPP 7.6.5 outlines where a building is requested to be removed from the MHI, at least one (1) of the following conditions must be met, as detailed in the table below.

Table 2 – Conditions for Removal of a Building from the Municipal Heritage Inventory

Policy Condition	Comment
Cultural Heritage Significance The cultural heritage significance of the place in the existing heritage assessment was erroneous.	The cultural heritage significance of the place was not erroneous in 2007 when last assessed.  It was noted at that time that the integrity of the historic setting had been compromised. Since then, the increased traffic on Guildford Road has led to an acceleration in the changes to the streetscape and its original neighbourhood context.  In 2007, the place was occupied and demonstrated its original use and much of its original detail. In 2023, the place is no longer habitable and original fabric has been stripped from the place and the remaining fabric is in poor condition.  To make the place viable for use would require removal of the structures across the rear of the property and replacement of much of the remaining fabric in the front rooms of the place. These changes would have an impact on the cultural heritage significance.
Condition  A structural condition report conducted by a registered structural engineer states that the structural integrity of the place has failed to the point where it cannot be rectified without the removal of a majority of its significant fabric. Note: The poor state of a place should not in itself be a reason for removal from MHI.	A structural engineer's report has not been prepared. The application does not seek to demolish the building based on its current structural condition.  The subject lot was originally acquired by the State for the purpose of delivering major road upgrades along Guildford Road and East Parade. Other properties acquired for the same purpose have previously been demolished in preparation for the future upgrades. The subject dwelling has been retained as far as practicable in the interim to allow for the final land requirements to be determined in order to understand the impact to the dwelling and the potential for retention.

#### Social or Historic Significance only

Where the heritage value is historic and/or social only the owner/applicant can demonstrate that it cannot practically be retained in its entirety or in part because:

- a) The location of the building on the site; or
- b) The limited Vehicular Access to the site and non-compliance with Australian Standards: or
- c) The inability to comply with the National Construction Codes Series e.g. ramps, corridor widths etc.; or d) The inability of the existing building structure or materials to be incorporated
- e) The inability of the existing building to support additional height and bulk to the intention of the locality as prescribed in the relevant planning policy.

into the new development; or

The primary planning justification for proposing the removal of the dwelling from the MHI and supporting its demolition fall within sub-clauses (a) and (d).

#### (a) The location of the building on the site

Main Roads have progressed development of plans for major road upgrades at the Guildford Road / East Parade intersection and now have an endorsed land requirement plan which confirms the extent of additional road widening necessary to facilitate the upgrades. The plan confirms that the road widening will materially impact on the fabric of the dwelling. As outlined in Figures 2 and 3 and Attachments 2 and 4, the existing dwelling is incompatible with the future MRS PRR reservation as it will encroach into the road reserve.

The existing dwelling will require partial demolition and significant modification affecting the primary frontage including the front room, steps, verandah and associated footings to in order to eliminate encroachment into the future road reserve and attempt to retain remaining portions of the dwelling. The brick and metal roof dwelling cannot be relocated to account for the road widening.

Hocking Heritage + Architecture considered that the identified historic value of the dwellings role in demonstrating the creation of a neighbourhood clustered around Guildford Road is no longer evident because of existing changes to the original streetscape character. The ultimate changes to the street layout and the proximity of the dwelling to the street edge will fundamentally alter the context and relationship of the dwelling to the streetscape, further diminishing its authenticity, original character and historic value.

Hocking Heritage + Architecture conclude that due to the extent of required modifications, the historical fabric and character of the dwelling will be impacted to a point where it is not considered that the dwelling could be sustained and retain its heritage values.

The planned road widening and major upgrades of the East Parade / Guildford Road intersection is an important piece of transport infrastructure as identified in the Perth and Peel@3.5million Central Sub-Regional Framework. Subsequently, the existing dwelling will need to be demolished and removed.

(d) The inability of the existing building structure or materials to be incorporated into the new development.

The existing dwelling cannot be incorporated into the proposed Mount Lawley HDP development mainly due to its location and incompatibility with the existing and proposed MRS PRR reservation. The location of the dwelling in proximity to the existing MRS PRR reservation is non-compliant with the R100 primary street setback requirement of 2.0m. The proposed MRS PRR reservation falls within front portions of the dwelling itself.

The removal of the dwelling will allow for a comprehensive redevelopment of the wider development site for the delivery of new housing supply though an active State Government initiative in line with priority State Government policy objectives.

There may be opportunity as part of the demolition of the dwelling to recycle materials for use in future developments.

As demonstrated above, the existing dwelling cannot practically be sustained and retain its heritage values. We respectfully request that Council approve the proposed demolition and remove the property from the City's MHI.

#### **Heritage Impact Statement**

A Heritage Impact Statement ('HIS') and archival photographic record have been prepared by Hocking Heritage + Architecture (Hocking) in support of the proposed demolition of the dwelling.

Refer Attachment Five - Heritage Impact Statement.



The HIS notes that the decline in the condition of the building has meant a significant loss of aesthetic values. The evolution of Guildford Road to a busy main road has meant that any connection with the former community has long been absent. The HIS also assesses the impact that the additional road widening will have on the dwelling and concludes that:

'the demolition of the portion of the building will result in the loss of authenticity and integrity of the building. The remainder of the building could not be sustained and retain its heritage values.'

In summary, the incremental change to the function of Guildford Road and the associated streetscape including the properties adjoining the subject lot over time has resulted in a diminishing of the significance and character of the original streetscape and dwelling. The modifications that will be required as a result of additional road upgrades planned for Guildford Road will result in the authenticity of the character, style and physical fabric of the dwelling being reduced to a point where it no longer holds a practical value of retention.

As recommended in the HIS, Hocking have prepared a detailed archival photographic record which captures the remaining aesthetic heritage values evident at the place.

Refer Attachment Six - Archival Photographic Record

#### 6.0 DEMOLITION METHODOLOGY

The demolition works will be completed in one stage and will include removal of all buildings and associated infrastructure.

At this juncture, a demolition contractor has not been appointed for the proposed works. Demolition methodology will be determined by the contractor, however, it is expected that the methodology will include:

- Service disconnections and rodent baiting;
- Site establishment and securing of the subject site;
- Removal of any hazardous materials (as required);
- Removal of ancillary structures, fittings, salvageable materials, deleterious materials etc;
- Vegetation removal and protection of trees to be retained;
- Further breakdown of demolished material or deconstructed structures; and
- Transport of demolished or deconstructed materials from the site.

Working hours for demolition are to be confirmed, but it is expected that works will be undertaken between the hours of 7am to 7pm Monday to Saturday (excluding public holidays), in accordance with the standard construction hours under the *Environmental Protection (Noise) Regulations 1997*. Any work outside these hours will require approval of an Out of Hours Noise Management Plan by the City.

It is expected that most vehicular movements associated with the demolition works will be via the laneway (removal of the rear fencing) and Stanley Street given Guildford Road is a busy regional road.

A more detailed Demolition Management Plan will be prepared by the appointed demolition contractor and will be submitted with the Demolition Permit application lodged with the City. This will include further details in relation to:

- Demolition methodology;
- Vegetation retention and protection;
- Noise and vibration management;
- Traffic management;
- Dust management;
- Safety and security; and
- Dilapidation surveys and reports.



As this Demolition Management Plan cannot be prepared until the demolition methodology is confirmed by the appointed contractor, it is considered that this matter can be appropriately dealt with via a condition of planning approval requiring the submission of the Demolition Management Plan for endorsement by the City, prior to lodgement of a Demolition Permit application.

#### 7.0 SUMMARY


This application seeks approval for complete demolition of the existing residential building and associated infrastructure at the subject site.

The demolition is proposed to facilitate widening of Guildford Road reserve to accommodate future planned major upgrades of the Guildford Road/ East Parade intersection and will also allow for the ultimate redevelopment of the site in line with priority State Government housing policy catered towards access and housing diversity.

The progression of these demolition works is an urgent priority, and therefore we respectfully request the City's assistance in progressing this application for development approval as quickly as possible, noting that:

- The demolition works are necessary to enable the widening of the Guildford Road Primary Regional Road reserve to accommodate planned major upgrades of the Guildford Road / East Parade intersection:
- Demolition of the existing dwelling is necessary to enable comprehensive redevelopment of a broader government landholding (HDP Mount Lawley site) for the purpose of improving housing choices and access;; and
- The existing dwelling at the subject site is vacant, boarded up and presents a safety hazard to the public.





Plan Information			Su	Survey Details			
Freehold Freehold		Fie	ld Records				
Plan Type	Deposited Plan			clared as Special Survey	NO		
Plan Purpo	ose Su	ubdivision		— Are	ea.		
Plan Hea	ding			C	miay Cartificata Das	udation 54	
ots 501-504 & 801-805			Su	ırvey Certificate - Reg	Julation 54		
					NICHOLAS KAITSE		
Locality 8	& Local Government			ne	reby certify that this plan is (a) survey; and	s accurate and is correct rep	resentation of the -
_ocality	ocality Mount Lawley			30	(b) calculations from me	asurements recorded in the f	
ocal Government City of Vincent				dertaken for the purposes itten law(s) in relation to v	of this plan and that it comp which it is lodged.	lies with the relevant	
						•	
9	ent of Planning, Land	is and Heritage					70
File Numbe	er			Lie	censed Surveyor		Date
Examination			Su.	rvov and Plan Notatio	an .		
_xammat	uon				rvey and Plan Notatio		
					OTE 2: THE DIMENSIONS CURATE SURVEYED AL	AND POSITIONS OF THIS IGNMENTS.	EASEMENT ARE BAS
Examined		n <sub>e</sub>	ate				
		08	<b></b>	Su	rvey Organisation		
	Approval			200	me	Land Surveys	
Planning A	uthority XX	XXX		2	dress	P.O BOX 746, Belmont	6984
Reference				- DATE:	one	94774477	
				Fa	x	94774499	
				20000000	nail	projects@landsurveys.net.au	
Delegated	under S. 16 P&D Act 20	05 Da	ate	Re	ference	2300903	
Plan App	ctor of Plans and Surveys proved of Plans and Surveys / A		ate				
Former T	enure Interests and I	Notifications					
Subject	Purpose	Statutory Reference		Origin	Land Burdened	Benefit To	Comments
6	EASEMENT (SEWERAGE)	SEC 27A OF THE T.F REGULATION 6	P & D ACT	D 75898	LOT 503	WATER CORPORATION	SEE NOTE
	GED VERSION SUBJECT E AUDIT & WAPC APP						

Am	enc	lme	nts

Version	Lodgement Type	Amendment Description	Authorised By	Date	

## Former Tenure

New Lot / Land	Parent Plan Number	Parent Lot Number	Title Reference	Subject Land Description
501	P 2001	Pt 247	2208 / 552	
	P 2001	Pt 248	2208 / 543	
	P 2001	Pt 249	2209 / 504	
	P 2001	Pt 250	2208 / 544	
	P 2001	Pt 251	2209 / 508	
	P 2001 DP 31182	Pt 252 Pt 402	2209 / 506 2209 / 506	
	DP 31182	Pt 403	2209 / 507	
	P 2001	Pt 254	2209 / 507	
	P 2001	Pt 255	1701 / 915	
	P 2001	Pt 256	2009 / 635	
	DP 426938	Pt 552	25557 555	
502	P 2001	Pt 234	1464 / 800	
	P 2001	Pt 235	1286 / 319	
	P 2001	Pt 236	1187 / 471	
	P 2001	Pt 237	2208 / 548	
	P 2001	Pt 238	2208 / 546	
	P 2001 P 2001	Pt 239 Pt 240	2208 / 549 2208 / 550	
	P 2001	Pt 241	2208 / 551	
	DP 31179	Pt 400	2208 / 540	
	DP 31179	Pt 401	2208 / 541	
	P 2001	Pt 243	2208 / 542	
	P 2001	Pt 244	2209 / 505	
	P 2001	Pt 245	2208 / 545	
	P 2001	Pt 246	2208 / 547	
503	DP 426937	Pt 550		
	DP 426937	Pt 551	0470 / 04	
	P 2001	Pt 207	2178 / 84	
	P 2001	Pt 208	1265 / 648	
50.4	P 2001	Pt 209	1265 / 649	
504	P 2001	Pt 202	1868 / 517	
	P 2001	Pt 203	1418 / 87	
004	P 2001	Pt 204	1887 / 420	
801	P 2001 P 2001	Pt 255 Pt 256	1701 / 915 2009 / 635	
	DP 426938	Pt 552	2009 / 033	
802	P 2001	Pt 247	2208 / 552	
	P 2001	Pt 248	2208 / 543	
	P 2001	Pt 249	2209 / 504	
	P 2001	Pt 250	2208 / 544	
	P 2001	Pt 251	2209 / 508	
	P 2001	Pt 252	2209 / 506	
	DP 31182	Pt 402	2209 / 506	
	DP 31182	Pt 403	2209 / 507	
	P 2001	Pt 254	2209 / 507	
803	P 2001	Pt 234	1464 / 800	
	P 2001	Pt 235	1286 / 319	
	P 2001	Pt 236	1187 / 471	
	P 2001	Pt 237	2208 / 548	
	P 2001	Pt 238	2208 / 546	
	P 2001	Pt 239	2208 / 549	
	P 2001	Pt 240	2208 / 550	
	P 2001	Pt 241	2208 / 551	
	DP 31179 DP 31179	Pt 400	2208 / 540	
	P 2001	Pt 401 Pt 243	2208 / 541 2208 / 542	
	P 2001	Pt 244	2208 / 542	
	P 2001	Pt 245	2208 / 545	
	P 2001	Pt 246	2208 / 547	
804	DP 426937	Pt 550		
	DP 426937	Pt 551		
	P 2001	Pt 207	2178 / 84	
	P 2001	Pt 208	1265 / 648	
	P 2001	Pt 209	1265 / 649	
805	P 2001	Pt 202	1868 / 517	
	D 0004	Pt 203	1418 / 87	
	P 2001 P 2001	Pt 204	1887 / 420	



-Current as at REVISION A


-Subject to change without notice
-Not intended for design use, a LANDGATE CERTIFIED
CORRECT copy should be obtained for such purposes.





DRAFT ONLY















P3138, LOT 254 (40) GUILDFORD RD, MOUNT LAWLEY Heritage Impact Statement



HOCKING HERITAGE + ARCHITECTURE

August 2023

#### **COPYRIGHT**

This Heritage Impact Statement for 40 Guildford Road, Mount Lawley is copyright to the Department of Planning Lands and Heritage, and Hocking Planning & Architecture Pty Ltd trading as Hocking Heritage + Architecture. This report cannot be reproduced, in whole or part, for any purposes apart from those permitted under the Copyright Act or used for professional or financial benefit by other professional consultants and/or building trade contractors without prior approval of Department of Planning Lands and Heritage, and Hocking Planning & Architecture Pty Ltd trading as Hocking H+A.

HHA Job No. 2023-08

Rev No	Author	Reviewer	Date
-	Prue Griffin	Grady O'Brien, DPLH Nick Bertone, City of Vincent	March 2023
А	Prue Griffin	Blake Rawlinson	August 2023
В	Prue Griffin		

## Contents

1.	Introduction	. 5
2.	Site Analysis	. 5
2.1	Location	5
2.2	Heritage Listing	7
2.3	Statement of Significance	7
3.	Subject Property	. 7
3.1	Physical Description	7
3.2	Streetscape	8
3.3	Elevations and Landscape	9
3.4	Internal Photographs	
3.5	History	15
4.	Proposed Development	15
5.	Assessment of Impact	17
6.	Conclusion	18

## Figures

Figure 1:	Location Map	6
Figure 2:	Lots 254 and 403 (40) Guildford Road Mount Lawley.	6
Figure 3:	View southwest on Guildford Road and vacant lot adjacent	8
Figure 4:	View southwest on Guildford Road towards the Mount Lawley subway	8
Figure 5:	View northeast on Guildford Road towards subject property	8
Figure 6:	View of the western elevation across the adjacent vacant lots	8
Figure 7:	View showing relationship to Guildford Road	
Figure 8:	View showing relationship to Guildford Road	8
igure 9:	Front Elevation	
Figure 10:	Front Elevation	9
Figure 11:	Front Elevation	9
igure 12:	Front Elevation	9
Figure 13:	Rear Elevation.	9
Figure 14:	Rear Elevation.	9
Figure 15:	West Elevation	
Figure 16:	East Elevation.	. 10
igure 17:	Front Door.	
Figure 18:	Hallway.	
Figure 19:	Bedroom	. 11
Figure 20:	Bedroom.	
Figure 21:	Bedroom	
Figure 22:	Bedroom 1.	
Figure 23:	Bedroom 2.	
Figure 24:	Bedroom 3.	
Figure 25:	Lounge Room	
igure 26:	Lounge Room	
Figure 27:	Lounge Room	
igure 28:	Lounge Room	
igure 29:	Dining Room (former kitchen)	
Figure 30:	Dining Room (former kitchen)	
Figure 31:	Kitchen	
igure 32:	Kitchen ceiling.	
igure 33:	Kitchen alcove	
igure 34:	Kitchen	
Figure 35:	Bathroom.	
igure 36:	Bathroom window	
Figure 37:	Road Widening Plan prepared by Main Roads	. 16



### 1. Introduction

This Heritage Impact Statement has been prepared at the request of the Department of Planning Lands and Heritage. Demolition of the building is proposed to enable future development of this site and adjacent properties on Guildford Road and East Parade, Mount Lawley for social housing.

Alongside the proposed development of the large parcel of land owned by the DPLH, Main Roads WA have assessed that Guildford Road needs to be widened along the southern side of Guildford Road to accommodate increased volume of vehicle traffic. The volume of traffic is also predicted to increase with any proposed development of the land held by DPLH. The widening will require resumption of portion of all lots on the south side of Guildford Road between Stanley Street and Pakenham Street.

The proposed resumption for road widening will require portion of the subject property at 40 Guildford Road to be removed.

40 Guildford Road was considered by the Department of Planning Lands and Heritage for inclusion in the State Register of Heritage Places in 2002 and was found to be below threshold for inclusion.

This heritage impact statement seeks to assess the impact on the cultural heritage significance of the place and some consideration of the wider impact on the streetscape. The report has been prepared following the guidelines established by the Heritage Council in their publication *Heritage Impact Statement – A Guide*.

## 2. Site Analysis

#### 2.1 Location

The property is located on the southeast side of Guildford Road in the block bound by Stanley Street and East Parade.

The property is located across two lots; lot 254 (40) on Plan 2001 and lot 403 on Deposited Plan 31182 as designated on Certificate of Title Volume 2209 Folio 50.

On either side of the lot are vacant lots where former residences of a similar age were located.




Figure 1: Location Map Courtesy Google Maps, accessed 21 October 2022



Figure 2: Lots 254 and 403 (40) Guildford Road Mount Lawley. COURTESY CITY OF VINCENT INTRAMAPS

### 2.2 Heritage Listing

The place has been identified by the City of Vincent as a Moderate Level of Significance which is described as:

Contributes to the heritage of the locality. Has some altered or modified elements, not necessarily detracting from the overall significance of the place.

Management Category B - Conservation Recommended

Consider for inclusion on the MHI (Heritage List) if owner/applicant consents to inclusion.

Туре	Status	Date	Category
Local Heritage Survey		12 Sept 2006	Category B
Heritage List	Adopted	12 Sept 2006	
Heritage Agreement	None		
State Register	Below Threshold	30 Nov 2001	
Register of National Estate			
Classified by the National Trust			

## 2.3 Statement of Significance

The City of Vincent prepared the following statement in 2006.

The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity.

## 3. Subject Property

## 3.1 Physical Description

This substantial single storey brick and corrugated zincalume residence demonstrates the Federation Queen Anne style. It is an asymmetric floor plan with a verandah wrapping the front and portion of the western side of the building.

It features an elaborate gable infill on the projecting bay and a bullnose verandah roof supported on turned posts. The verandah is brick paving on sand infill that is contained by limestone foundations. The original timber verandah has been removed although the steps to the main entry do remain.

Internally the place retains its original floor plan with some additions across the rear. In general, there is little evidence of any original finishes as the place has been stripped of all architectural details, such as architraves, skirtings and the majority of the floorboards. Windows are all broken and some window frames have been completely removed. On the eastern elevation there is evidence of failed brickwork.

The place is in very poor condition and graffiti is evident internally and externally.

The garden shows no evidence of any formal planting and although some trees are large specimens there are not species of any particular rarity or merit.

## 3.2 Streetscape



Figure 3: View southwest on Guildford Road and vacant lot adjacent.



Figure 4: View southwest on Guildford Road towards the Mount Lawley subway.



Figure 5: View northeast on Guildford Road towards subject property.



Figure 6: View of the western elevation across the adjacent vacant lots.



Figure 7: View showing relationship to Guildford Road.



Figure 8: View showing relationship to Guildford Road.

## 3.3 Elevations and Landscape

The majority of the exterior of the original residence still demonstrates the brick construction with concrete bands and some remnants of tuckpointing. Large areas of the external walls have graffiti and the surrounding grounds are in poor condition with some mature trees.



Figure 9: Front Elevation



Figure 10: Front Elevation



Figure 11: Front Elevation



Figure 12: Front Elevation



Figure 13: Rear Elevation.



Figure 14: Rear Elevation.







Figure 16: East Elevation.

## 3.4 Internal Photographs

The interior of the property was poorly lit and difficult to navigate because of the removed floorboards and accumulation of debris. The following photographs demonstrate that the majority of detail has been removed. Apart from some original floorboards there are no architraves, skirtings or doors. There is also asbestos sheeting in the rear of the building.



Figure 17: Front Door.



Figure 18: Hallway.



Figure 19: Bedroom



Figure 20: Bedroom.



Figure 21: Bedroom



Figure 22: Bedroom 1.




Figure 23: Bedroom 2.




Figure 24: Bedroom 3.



Figure 25: Lounge Room.



Figure 26: Lounge Room.




Figure 27: Lounge Room




Figure 28: Lounge Room



Figure 29: Dining Room (former kitchen)



Figure 30: Dining Room (former kitchen)



Figure 31: Kitchen.



Figure 32: Kitchen ceiling.



Figure 33: Kitchen alcove.




Figure 34: Kitchen.



Figure 35: Bathroom.



Figure 36: Bathroom window.

#### 3.5 History

This place was built c1904 as a private residence. It was used for that purpose until its declining condition made it uneconomic to repair. The place was closed and has been accessed by vagrants for some years and been stripped of any original detail.<sup>1</sup>

The adjacent residences on Guildford Road have been demolished in the early 2000s leaving the place isolated within cleared lots to the north and south.

## 4. Proposed Development

The Department of Planning Lands and Heritage are proposing to develop this site and adjoining lots for future social housing. The form and scale of the development has not been finalised at this stage. Nevertheless, it is a requirement of the new development that the site is cleared to enable optimum occupancy of the site.

Alongside the proposed development of the large parcel of land owned by the DPLH, Main Roads WA have assessed that Guildford Road needs to be widened along the southern side of Guildford Road to accommodate the current increased volume of vehicle traffic. The volume of traffic is also predicted to increase with any proposed development of the land held by DPLH. The widening will require resumption of portion of all lots on the south side of Guildford Road between Stanley Street and Pakenham Street.

Specifically, the proposed resumption for road widening will require portion of the subject property at 40 Guildford Road to be removed.

Therefore the subject property is required to be removed for future development of the site and because it will hamper the road widening which is required for the ongoing safety and amenity of the community.

Refer to the Archival Record for 40 Guildford Road, Mount Lawley, May 2023.






Figure 37: Road Widening Plan prepared by Main Roads.



## 5. Assessment of Impact

The development application is seeking to remove the building from the City's Municipal Heritage Inventory (MHI) to enable demolition of the building.

Under Clause 2 of the City of Vincent's Heritage Policy 7.6.5, amendments can be made to the MHI to accompany applications for demolition.

The requirements under Figure 1 of that policy state that to delete a building from the MHI, the application would be to demonstrate **one** of the following

- The cultural heritage significance of the place in the existing heritage assessment was erroneous.
- A structural condition report conducted by a registered structural engineers states that the structural integrity of the place has failed to the point where it cannot be rectified without the removal of a majority of its significant fabric. Note: The poor state of a place should not in itself be a reason for removal from MHI
- Where the heritage value is historic and/or social only the owner/applicant can demonstrate that it cannot practically be retained in its entirety or in part

RATIONALE FOR REMOVAL FROM THE MHI	RATIONALE
The cultural heritage significance of the place in the existing heritage assessment was erroneous.	The cultural heritage significance of the place was not erroneous in 2007 when last assessed.
	It was noted at that time that the integrity of the historic setting had been compromised. Since then, the increased traffic on Guildford Road has led to an acceleration in the changes to the streetscape and its original neighbourhood context.
	In 2007, the place was occupied and demonstrated its original use and much of its original detail. In 2023, the place is no longer habitable and original fabric has been stripped from the place and the remaining fabric is in poor condition.
	To make the place viable for use would require removal of the structures across the rear of the property and replacement of much of the remaining fabric in the front rooms of the place. These changes would have an impact on the cultural heritage significance.
A structural condition report conducted by a registered structural engineers states that the structural integrity of the place has failed to the point where it cannot be rectified without the removal of a majority of its significant fabric.  Note: The poor state of a place should not in itself be a reason for removal from MHI	A structural engineer's report has not been prepared.
Where the heritage value is historic and/or social only the owner/applicant can demonstrate that it cannot practically be retained in its entirety or in part	The heritage values of the place were determined to be in part the aesthetic value of its Federation Arts and Crafts style which is no



longer apparent because of the loss of original detail.

The historic and social values of the place were identified in the remaining form and fabric of the place. This has now been significantly diminished through vandalism and the deterioration of the condition of the remaining fabric.

The identified historic value of its role in demonstrating the creation of a neighbourhood clustered around Guildford Road is no longer evident.

In addition to the above requirements of the Heritage Policy 7.6.5 an assessment of the impact of demolition on the heritage values of the place has been determined through the values designated in the 2006 Heritage Assessment for the Local Heritage Survey.

The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity.

The decline in the condition of the building has meant a significant loss of aesthetic values and the evolution of Guildford Road to a busy main road has meant that any connection with the former community has long been absent.

HERITAGE VALUE	ASSESSMENT OF IMPACT
The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity	The demolition of the building will lead to a loss of the building fabric but its degraded state has meant its heritage values are already diminished from the 2006 statement.  The association with the original development has long been absent because of the changing nature of the adjacent properties on Guildford Road.
	The future road widening of Guildford Road will have a further impact on the heritage value associated with the former streetscape and community which formerly lived adjacent.

#### 6. Conclusion


The demolition of the building at 40 Guildford Road, Mount Lawley is supported.

The road widening is essential for the safety and amenity of the wider community. Demolition of portion of the building will result in the loss of authenticity and integrity of the building. The remainder of the building could not be sustained and retain its heritage values.

The preparation of an archival photographic record will capture any remaining aesthetic heritage values evident at the place.

element.

### ATTACHMENT FIVE - ROAD WIDENING REQUIREMENTS OVERLAY



Lot 254 Guildford Road, Mount Lawley

element.

### ATTACHMENT SIX - ARCHIVAL PHOTOGRAPHIC RECORD





P3138, LOT 254 (40) GUILDFORD RD, MOUNT LAWLEY Photographic Archival Record



**HOCKING HERITAGE + ARCHITECTURE** 

March 2023

#### Copyright

This report is copyright to the Department of Planning Lands and Heritage and Hocking Heritage + Architecture. This report cannot be reproduced, in whole or in part, for any purposes apart from those permitted under the Copyright Act or use for professional or financial benefit by other professional consultants and / or building trade contractors without prior approval of the Department of Planning Lands and Heritage and Hocking Heritage + Architecture.

HHS Job No. 2023-08

Rev No	Author	Reviewer		Date
-	Prue Griffin	Grady O'Brien	DPLH	March 2023



# Contents

Conte	ents	3
Figure	·\$	4
1.0	Background	
2.0	Statement of Significance	6
3.0	Location	6
4.0	Brief History	9
4.1	Occupants and owners	11
5.0	Photographs	14
5.1	Streetscape	14
5.2	Elevations and Landscape	16
5.3	Internal Photographs	20
6.0	Bibliography	27
Appe	ndix A – Certificates of Title	28



# Figures

Figure 1:	Location Plan	
Figure 2:	Lots 254 and 403 (40) Guildford Road Mount Lawley	
Figure 3:	Site Plan	8
Figure 4:	Sewerage Plan Sheet 226, 1917	10
Figure 5:	Sewerage plan of the property, 1917	12
Figure 6:	Aerial photograph, 1965	12
Figure 7:	Floor Plan	
Figure 8:	View southwest on Guildford Road and vacant lot adjacent	14
Figure 9:	View southwest on Guildford Road towards the Mount Lawley subway	
Figure 10:	View northeast on Guildford Road towards subject property	
Figure 11:	View of the western elevation across the adjacent vacant lots	
Figure 12:	View from the lane at the rear of the property.	
Figure 13:	View from the lane at the rear of the property.	
Figure 14:	View from the lane showing the rear property fence and planting	
Figure 15:	View from the lane to the western elevation	
Figure 16:	View showing relationship to Guildford Road	
Figure 17:	View showing relationship to Guildford Road	
Figure 18:	Properties on the northern side of Guildford Road.	
Figure 19:	View to buildings on the northern side of Guildford Road.	
Figure 20:	Front Elevation	
Figure 21:	Front Elevation	
Figure 22:	Front Elevation	
-	Front Elevation	
Figure 23:		
Figure 24:	Front Elevation showing verandah	
Figure 25:	Front Elevation showing original steps	
Figure 26:	Rear Elevation.	
Figure 27:	Rear Elevation.	
Figure 28:	Rear Elevation.	
Figure 29:	Rear Elevation	
Figure 30:	West Elevation	
Figure 31:	East Elevation.	
Figure 32:	Remnant planting on the east side of the house	
Figure 33:	Overgrown creeper on the west elevation	
Figure 34:	Rubble and degraded plants on the west side of the lot	
Figure 35:	Fenced western side of the lot and some remnant hardscaping	
Figure 36:	View of the mature trees in the backyard from the lane	
Figure 37:	Back yard	
Figure 38:	Front Door.	
Figure 39:	Hallway	
Figure 40:	Hallway	
Figure 41:	Hallway	
Figure 42:	Bedroom	21
Figure 43:	Bedroom	21
Figure 44:	Bedroom	21
Figure 45:	Bedroom 1	21
Figure 46:	Bedroom 1	21
Figure 47:	Detail of floorboards	
Figure 48:	Bedroom 2	22
Figure 49:	Bedroom 3	22
Figure 50:	Lounge Room	22
Figure 51:	Lounge Room	
Figure 52:	Lounge Room	
Figure 53:	Lounge Room	
Figure 54:	Dining Room (former kitchen)	
_	- '	



Figure 55:	Dining Room (former kitchen)	23
Figure 56:	Kitchen.	24
Figure 57:	Kitchen ceiling	24
Figure 58:	Kitchen alcove	
Figure 59:	Kitchen.	24
Figure 60:	Sleepout looking through to Dining Room.	
Figure 61:	Sleepout looking through to Dining Room.	
Figure 62:	Bathroom door and ceiling.	
Figure 63:	Bathroom.	
Figure 64:	Bathroom.	
Figure 65:	Bathroom window.	
	=	



# 1.0 Background

This photograph archival record has been prepared at the request of the Department of Planning Lands and Heritage. Demolition is proposed for the building to enable future development of this site and adjacent properties on Guildford Road and East Parade, Mount Lawley.

This place was considered by the Department of Planning Lands and Heritage for inclusion in the State Register of Heritage Places in 2002 and was found to be below threshold for inclusion.

The place has been identified by the City of Vincent as a Moderate Level of Significance which is described as:

Contributes to the heritage of the locality. Has some altered or modified elements, not necessarily detracting from the overall significance of the place.

Management Category B - Conservation Recommended

Consider for inclusion on the MHI (Heritage List) if owner/applicant consents to inclusion.

This Archival Record has been prepared to enable the development of the site whilst recognising the heritage values of the place.

# 2.0 Statement of Significance

The City of Vincent have prepared the following statement.

The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity.

## 3.0 Location

The property is located on the south east side of Guildford Road in the block bound by Stanley Street and East Parade.

The property is located across two lots; lot 254 (40) on Plan 2001 and lot 403 on Deposited Plan 31182 as designated on Certificate of Title Volume 2209 Folio 50.

On either side of the lot are vacant lots where former residences of a similar age were located.






Figure 1: Location Plan

#### COURTESY NEARMAP



Figure 2: Lots 254 and 403 (40) Guildford Road Mount Lawley.

#### COURTESY CITY OF VINCENT INTRAMAPS






Figure 3: Site Plan



# 4.0 Brief History

This history has been expanded from the research prepared for the City of Vincent Local Heritage Survey. Acknowledgement is extended to the authors of that documentation.

This section of Guildford Road is part of the East Norwood Estate which was developed in 1898, on part of Locations A4 and A5, on the eastern side of the Fremantle-Guildford Railway line, in the East Perth/Mt Lawley area. The subdivision was carried out by surveyors Crossland & Hardy on behalf of the Perth (WA) Estate Company Limited of 364 Hay Street.

The strong demand for new housing was a result of the population boom created by the gold discoveries in the State. One member of the Perth (WA) Estate Company was Zebina Lane, who was an engineer and mine owner at the Great Boulder mines, and one of a number of people who made money in gold mining and reinvested it in land developments during this period. The Company had previously developed the adjoining Westralia Estate on the west side of the railway line on Location A4. The estate was promoted as having 'splendid building lots', 'made roads' and 'river frontages'. In the latter case these were the larger blocks along Joel Terrace which were expected to attract the wealthier buyers. It is evident from the subdivision map that this was not one of the earliest blocks sold, the earliest being those used for 'spec' and rental housing along the railway line (East Parade), Bramall and Summers Street.

The estate's boundary nearest to the subject place was Stanley Street (two house blocks from No. 40), which later became the boundary between the Town of Vincent (formed 1995) and that portion of Mount Lawley which is in the City of Stirling. This section of Guildford Road was listed in the Wise's Post Office Directories initially as 'Guildford old road' and by 1905 it was known as 'Old Guildford Road' and listed in conjunction with Lord Street. Around 1908 it became known as 'Guildford Road, Norwood' and it remained so until the 1940's.

No 40 Guildford Road, was well positioned for access to Perth's train system via the nearby Mount Lawley Station. Then in 1924 a single tram track was laid from the tram terminus on the corner of Lord and Lincoln Streets through the Mount Lawley Subway to Maylands. In 1939 this line was duplicated, and the Subway widened to accommodate the second track. This further improved access to the city.

In 1925 the resident was Herbert Illingworth. At that time the area around the Mount Lawley Subway (just a street block away) was a thriving village. The shops and businesses also listed in the Directories were No. 1 Guildford Road Methodist Church, No. 3 plumber, No. 5 Laundry, Nos. 8 - 10 butcher, No. 12 fancy goods and draper, No. 14 confectioner and grocer, No. 15 newsagent, stationer, tobacconist and State Savings Bank agency, No. 18 tobacco and fancy goods and No. 19 butcher. In 1.

The subdivision plan for this property was approved in 1898 and lots were purchased from the developer British Westralia Syndicate Limited.<sup>2</sup> Lots 253 and 254 were purchased in 1902 by Alice Victoria McColl.<sup>3</sup>

Alice Victoria McColl (c1863-1914) was the wife of railway employee, Stawell Austral McColl (c1861-1916). From the available evidence in the Post Office Directories and Electoral Rolls the place was built in 1904 as A. McColl is recorded living in Guildford Road in 1905. The builder or architect of the residence has not been determined. It is likely that a local builder, such as John Berne Hawkins who lived in Guildford Road, constructed the home in accordance with readily available plans from pattern books that were in common usage at the time. The plan form and remaining detail of the building indicate that the home was of some quality and not a cottage for occupants of limited

<sup>&</sup>lt;sup>3</sup> Certificate of Title, 161/20, Landgate.



9

Place 3818 House, City of Vincent InHerit database entry. Adopted 2006.

<sup>&</sup>lt;sup>2</sup> Certificate of Title, 161/20, Landgate.

income. This conclusion is also supported by the evidence that the residence occupied more than one lot it and was set in a more expansive garden setting.<sup>4</sup>




Figure 4: Sewerage Plan Sheet 226, 1917.

COURTESY SROWA SERIES 634 CONS 4156 ITEM 0226

The McColls appear to have lived in the place until c1911 and subsequently leased the place to tenants. A newspaper article from March 1911 records that Stawell and Alice McColl were living in St Georges Terrace Perth at that time.<sup>5</sup>

Post Office Directories record that there was a rapid turnover of occupants between 1912 and 1915 and was then occupied by caterer Andrew Cavanagh and his wife Jane until 1918.

In 1914, Alice McColl died, and the property transferred to Stawell McColl, and on his death in 1916 the property was transferred to their children, Alice Sophia McColl and Archibald Dougald McColl.<sup>6</sup> The siblings continued to lease the property to tenants, traveller Herbert Illingworth and his wife Ethel Illingworth from 1919 to 1926.<sup>7</sup>

In 1926, the property was transferred to clerk Frederick William James Joyce (c1893-1973) and his wife Eunice Hilda Joyce, nee Bevan (c1895-1977). The couple married in 1914 and had at least four children and lived at this house until the 1970s. Frederick Joyce died in 1973 and Eunice lived on in the house until at least 1975 when the place was transferred to draftsman William Richard Marks and

Post Office Directories, State Library of WA, <u>Post office directories | State Library of Western Australia</u> (slwa.wa.gov.au) accessed February 2023.



10

Sewerage Plan Sheet 226 shows the width of the lot is larger than the majority of the housing lots adjacent.

<sup>5</sup> The West Australian, 29 March 1911, p. 4.

<sup>6</sup> Certificates of Title, 682/184 and 682/185, Landgate.

Public Relations Officer Lynette Marks.<sup>8</sup> The couple lived at the house until 1986 when the house was transferred to the Western Australian Planning Commission.<sup>9</sup> With the transfer of the property to the WAPC the residence was leased to tenants.

Aerial photographs from the mid 20<sup>th</sup> century indicate that the extent and form of the residence have not changed considerably since that time. The WAPC and its subsequent authorities maintained the property when it was occupied by tenants including the replacement of the roof cladding in the late 1980s.

The physical evidence suggests that the timber verandah was replaced in the late 1980s with the current verandah which is brick laid on sand.

The houses located to the south of the 40 Guildford Road were demolished in 2000, and the house to the north was demolished c2009. The original residential context of this portion of Guildford Road has been lost as a result of these changes.

The residence has been unoccupied for several years and is in a very poor condition.

### 4.1 Occupants and owners


DATE	OWNERS	OCCUPANT	
1898 - 1902	British Westralia Syndicate Limited	None	
1902 - 1918	Alice Victoria McColl	<ul> <li>1905 – 1911 Stawell Austral McColl and Alice Victoria McColl.</li> <li>1912 William J Franz</li> <li>1913 Frederick W Koeppe</li> <li>1914 John Dillon and Haswell Bromley</li> <li>1915 - 1918 Andrew and Jane Cavanagh</li> </ul>	
1918 - 1926	Alice Sophia McColl and Archibald Dougald McColl	1919 - 1926 Herbert Illingworth	
1926 – 1975	Frederick William Joyce and Eunice Hilda Joyce.	Frederick William Joyce (until 1973) and Eunice Hilda Joyce.	
1975 - 1986	William Richard Marks and Theresa Barbara Marks	William Richard Marks and Theresa Barbara Marks	
1986 - 2001	Western Australian Planning Commission	Various	
2001 – 2023	Western Australian Planning Commission (Dept of Planning Lands and Heritage)	Various and vacant	


<sup>9</sup> Certificate of Title 1070/301, Landgate.



11

<sup>8</sup> Certificate of Title 1033/111, Landgate.








Figure 7: Floor Plan



# 5.0 Photographs

The following images were taken on 8 March 2023 by Hocking Heritage + Architecture. No access was available to the roof space or underfloor space.

## 5.1 Streetscape



Figure 8: View southwest on Guildford Road and vacant lot adjacent.



Figure 9: View southwest on Guildford Road towards the Mount Lawley subway.



Figure 10: View northeast on Guildford Road towards subject property.



Figure 11: View of the western elevation across the adjacent vacant lots.



Figure 12: View from the lane at the rear of the property.



Figure 13: View from the lane at the rear of the property.



Figure 14: View from the lane showing the rear property fence and planting.



Figure 15: View from the lane to the western elevation.



Figure 16: View showing relationship to Guildford Road.



Figure 17: View showing relationship to Guildford Road.



Figure 18: Properties on the northern side of Guildford Road.



Figure 19: View to buildings on the northern side of Guildford Road.

### 5.2 Elevations and Landscape

The majority of the exterior of the original residence still demonstrates the brick construction with concrete bands and some remnants of tuckpointing. Large areas of the external walls have graffiti and the surrounding grounds are in poor condition although there are some mature trees.



Figure 20: Front Elevation



Figure 21: Front Elevation



Figure 22: Front Elevation.



Figure 23: Front Elevation.



Figure 24: Front Elevation showing verandah.



Figure 25: Front Elevation showing original steps.



Figure 26: Rear Elevation.



Figure 27: Rear Elevation.





Figure 28: Rear Elevation.



Figure 29: Rear Elevation.



Figure 30: West Elevation.



Figure 31: East Elevation.



Figure 32: Remnant planting on the east side of the house



Figure 33: Overgrown creeper on the west elevation.



Figure 34: Rubble and degraded plants on the west side of the lot.



Figure 35: Fenced western side of the lot and some remnant hardscaping.



Figure 36: View of the mature trees in the backyard from the lane.



Figure 37: Back yard.

### 5.3 Internal Photographs

The interior of the property was poorly lit and difficult to navigate because of the removed floorboards and accumulation of debris. The following photographs demonstrate that the majority of detail has been removed. Apart from some original floorboards there are no architraves, skirtings or doors. There is also asbestos sheeting in the rear of the building.



Figure 38: Front Door.



Figure 39: Hallway.



Figure 40: Hallway.



Figure 41: Hallway.





Figure 42: Bedroom



Figure 43: Bedroom.



Figure 44: Bedroom



Figure 45: Bedroom 1.



Figure 46: Bedroom 1.



Figure 47: Detail of floorboards.





Figure 48: Bedroom 2.



Figure 49: Bedroom 3.



Figure 50: Lounge Room.



Figure 51: Lounge Room.




Figure 52: Lounge Room



Figure 53: Lounge Room



Figure 54: Dining Room (former kitchen)



Figure 55: Dining Room (former kitchen)







Figure 57: Kitchen ceiling.



Figure 58: Kitchen alcove.




Figure 59: Kitchen.



Figure 60: Sleepout looking through to Dining Room.



Figure 61: Sleepout looking through to Dining Room.



Figure 62: Bathroom door and ceiling.



Figure 63: Bathroom.



Figure 64: Bathroom.



Figure 65: Bathroom window.

# 6.0 Bibliography

c7e94f3cf953

(1833-2020). The West Australian.

Australian Electoral Commission. (1903-1980). Electoral Rolls. Australia.

Department of Planning Lands and Heritage. (2001, June 5). *Place 3818 inHerit Record From*. Retrieved from InHerit database: http://inherit.stateheritage.wa.gov.au/Public/Inventory/Details/dfea3f29-5fd0-47f9-97cb-

Erickson, R. (Ed.). (1988). The Bicentennial Dictionary of Western Australians pre-1829-1888. Perth, WA: UWA Press.


Landgate. (1953-2022). Map Viewer Aerial Photographs. Retrieved March 2021, from https://www.landgate.wa.gov.au/bmvf/app/mapviewer/

Landgate. (n.d.). Certificates of Title and Survey Information. From https://www.landgate.wa.gov.au

Wise's Western Australia Post Office Directories. (1893-1949). Wise's Directories. Perth, WA, Australia: H. Wise & Co. Pty Ltd. Retrieved from https://slwa.wa.gov.au/explore-discover/wa-heritage/post-office-directories







P3138, LOT 254 (40) GUILDFORD RD, MOUNT LAWLEY Photographic Archival Record



**HOCKING HERITAGE + ARCHITECTURE** 

March 2023

#### Copyright

This report is copyright to the Department of Planning Lands and Heritage and Hocking Heritage + Architecture. This report cannot be reproduced, in whole or in part, for any purposes apart from those permitted under the Copyright Act or use for professional or financial benefit by other professional consultants and / or building trade contractors without prior approval of the Department of Planning Lands and Heritage and Hocking Heritage + Architecture.

HHS Job No. 2023-08

Rev No	Author	Reviewer		Date
-	Prue Griffin	Grady O'Brien	DPLH	March 2023



## Contents

Conte	ents	3
	S	
1.0	Background	
2.0	Statement of Significance	ć
3.0	Location	é
4.0	Brief History	9
4.1	Occupants and owners	. 11
5.0	Photographs	. 14
5.1	Streetscape	. 14
5.2	Elevations and Landscape	. 16
5.3	Internal Photographs	. 20
6.0	Bibliography	. 27
Appei	ndix A – Certificates of Title	. 28



Figure 1: Location Plan	Figures		
Figure 2: Lots 254 and 403 (40) Guildford Road Mount Lawley. Figure 3: Site Plan	Figure 1:	Location Plan	7
Figure 3: Site Plan	-		
Figure 4: Sewerage Plan Sheet 226, 1917.   11 Figure 5: Sewerage plan of the property, 1917.   12 Figure 6: Aerial photograph, 1965.   17 Figure 7: Floor Plan   1.5 Figure 8: View southwest on Guildford Road and vacant lot adjacent.   1.5 Figure 9: View southwest on Guildford Road towards the Mount Lawley subway   1.5 Figure 10: View northeast on Guildford Road towards subject property.   1.5 Figure 11: View of the western elevation across the adjacent vacant lots.   1.5 Figure 12: View from the lane at the rear of the property.   1.5 Figure 13: View from the lane at the rear of the property.   1.5 Figure 14: View from the lane at the rear of the property.   1.5 Figure 15: View from the lane showing the rear property fence and planting.   1.5 Figure 16: View showing relationship to Guildford Road.   1.7 Figure 17: View showing relationship to Guildford Road.   1.7 Figure 18: Properties on the northern side of Guildford Road.   1.7 Figure 19: View to buildings on the northern side of Guildford Road.   1.7 Figure 20: Front Elevation.   1.7 Figure 21: Front Elevation.   1.7 Figure 22: Front Elevation.   1.7 Figure 23: Front Elevation.   1.7 Figure 24: Front Elevation showing verandah.   1.7 Figure 25: Front Elevation showing verandah.   1.7 Figure 26: Rear Elevation showing original steps.   1.7 Figure 27: Rear Elevation.   1.7 Figure 28: Rear Elevation.   1.7 Figure 29: Rear Elevation.   1.7 Figure 30: Rear Elevation.   1.7 Figure 31: Foot Elevation.   1.7 Figure 32: Remand planting on the east side of the house.   1.7 Figure 33: Overgrown creeper on the west elevation.   1.7 Figure 34: Rubble and degraded plants on the west side of the lot.   1.7 Figure 35: Fenced western side of the lot and some remnant hardscaping.   1.7 Figure 37: Back yard.   1.7 Figure 38: Front Door.   22 Figure 39: Hallway.   22 Figure 41: Hallway.   22 Figure 42: Bedroom.   2	•		
Figure 6: Aerial photograph, 1965. 1.1 Figure 7: Floor Plan	•	Sewerage Plan Sheet 226, 1917	10
Figure 7: Floor Plan	-	Sewerage plan of the property, 1917.	12
Figure 7: Floor Plan	Figure 6:		
Figure 9: View southwest on Guildford Road towards the Mount Lawley subway.  1. Figure 10: View northeast on Guildford Road towards subject property.  1. Figure 11: View of the western elevation across the adjacent vacant lots.  1. Figure 12: View from the lane at the rear of the property.  1. Figure 13: View from the lane at the rear of the property.  1. Figure 14: View from the lane showing the rear property fence and planting.  1. Figure 15: View from the lane to the western elevation.  1. Figure 16: View showing relationship to Guildford Road.  1. Figure 17: View showing relationship to Guildford Road.  1. Figure 18: Properties on the northern side of Guildford Road.  1. Figure 19: View to buildings on the northern side of Guildford Road.  1. Figure 20: Front Elevation.  1. Figure 21: Front Elevation.  1. Figure 22: Front Elevation.  1. Figure 23: Front Elevation.  1. Figure 24: Front Elevation.  1. Figure 25: Front Elevation showing verandah.  1. Figure 26: Rear Elevation showing original steps.  1. Figure 27: Rear Elevation.  1. Figure 28: Rear Elevation.  1. Figure 29: Rear Elevation.  10: Figure 29: Rear Elevation.  11: Figure 29: Rear Elevation.  12: Figure 29: Rear Elevation.  13: Figure 29: Rear Elevation.  14: Figure 29: Rear Elevation.  15: Figure 29: Rear Elevation.  16: Figure 29: Rear Elevation.  17: Figure 29: Rear Elevation.  18: Figure 29: Rear Elevation.  19: Figure 29: Rear Elevation.  10: Figure 29: Rear Elevation.  11: Figure 29: Rear Elevation.  12: Figure 31: Fast Elevation.  13: Figure 32: Rear Elevation.  14: Figure 33: Overgrown creeper on the west side of the house.  15: Figure 34: Remnant planting on the east side of the house.  16: Figure 35: Fenced western side of the lot and some remnant hardscaping.  17: Figure 36: View of the mature trees in the backyard from the lane.  18: Figure 37: Back yard.  19: Figure 38: Front Door.  19: Figure 39: Hallway.  19: Figure 41: Hallway.  20: Figure 41: Hallway.  21: Figure 42: Bedroom.  22: Figure 43: Bedroom.	Figure 7:		
Figure 9: View southwest on Guildford Road towards the Mount Lawley subway.  1. Figure 10: View northeast on Guildford Road towards subject property.  1. Figure 11: View of the western elevation across the adjacent vacant lots.  1. Figure 12: View from the lane at the rear of the property.  1. Figure 13: View from the lane at the rear of the property.  1. Figure 14: View from the lane showing the rear property fence and planting.  1. Figure 15: View from the lane to the western elevation.  1. Figure 16: View showing relationship to Guildford Road.  1. Figure 17: View showing relationship to Guildford Road.  1. Figure 18: Properties on the northern side of Guildford Road.  1. Figure 19: View to buildings on the northern side of Guildford Road.  1. Figure 20: Front Elevation.  1. Figure 21: Front Elevation.  1. Figure 22: Front Elevation.  1. Figure 23: Front Elevation.  1. Figure 24: Front Elevation.  1. Figure 25: Front Elevation showing verandah.  1. Figure 26: Rear Elevation showing original steps.  1. Figure 27: Rear Elevation.  1. Figure 28: Rear Elevation.  1. Figure 29: Rear Elevation.  10: Figure 29: Rear Elevation.  11: Figure 29: Rear Elevation.  12: Figure 29: Rear Elevation.  13: Figure 29: Rear Elevation.  14: Figure 29: Rear Elevation.  15: Figure 29: Rear Elevation.  16: Figure 29: Rear Elevation.  17: Figure 29: Rear Elevation.  18: Figure 29: Rear Elevation.  19: Figure 29: Rear Elevation.  10: Figure 29: Rear Elevation.  11: Figure 29: Rear Elevation.  12: Figure 31: Fast Elevation.  13: Figure 32: Rear Elevation.  14: Figure 33: Overgrown creeper on the west side of the house.  15: Figure 34: Remnant planting on the east side of the house.  16: Figure 35: Fenced western side of the lot and some remnant hardscaping.  17: Figure 36: View of the mature trees in the backyard from the lane.  18: Figure 37: Back yard.  19: Figure 38: Front Door.  19: Figure 39: Hallway.  19: Figure 41: Hallway.  20: Figure 41: Hallway.  21: Figure 42: Bedroom.  22: Figure 43: Bedroom.	Figure 8:	View southwest on Guildford Road and vacant lot adjacent	14
Figure 10: View northeast on Guildford Road towards subject property.  Figure 11: View of the western elevation across the adjacent vacant lots.  Figure 12: View from the lane at the rear of the property.  Figure 13: View from the lane at the rear of the property.  Figure 14: View from the lane showing the rear property fence and planting.  It Figure 15: View from the lane to the western elevation.  Figure 16: View showing relationship to Guildford Road.  Figure 17: View showing relationship to Guildford Road.  Figure 18: Properties on the northern side of Guildford Road.  Figure 19: View to buildings on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation.  Figure 25: Front Elevation showing verandah.  Figure 26: Rear Elevation showing verandah.  Figure 27: Rear Elevation.  Figure 28: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 32: Rear Elevation.  Figure 33: Overgrown creeper on the east side of the house.  Figure 34: Rubble and degraded plants on the west side of the lot.  Figure 35: Fronce dwestern side of the lot and some remnant hardscaping.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 40: Hallway.  Figure 41: Hallway.  Figure 42: Bedroom.  20: Figure 43: Bedroom.  21: Figure 44: Bedroom.  22: Figure 44: Bedroom.  23: Figure 44: Bedroom.  24: Figure 44: Bedroom.	Figure 9:		
Figure 12: View from the lane at the rear of the property. Figure 13: View from the lane at the rear of the property. Is Figure 14: View from the lane showing the rear property fence and planting. Figure 15: View from the lane to the western elevation. Is Figure 16: View showing relationship to Guildford Road. Is Figure 17: View showing relationship to Guildford Road. Is Figure 18: Properties on the northern side of Guildford Road. Is Figure 19: View to buildings on the northern side of Guildford Road. Is Figure 20: Front Elevation. Is Figure 21: Front Elevation. Is Figure 22: Front Elevation. Is Figure 23: Front Elevation. Is Figure 24: Front Elevation showing verandah. Is Figure 25: Front Elevation showing original steps. Is Figure 26: Rear Elevation. Is Figure 27: Rear Elevation. Is Figure 28: Rear Elevation. Is Figure 29: Rear Elevation. Is Figure 30: West Elevation. Is Figure 31: East Elevation. Is Figure 32: Remnant planting on the east side of the house. Is Figure 33: Overgrown creeper on the west slevation. Is Figure 34: Rubble and degraded plants on the west side of the lot. Is Figure 36: View of the mature trees in the backyard from the lane. Is Figure 37: Back yard. Is Figure 38: Front Door. Is Figure 39: Hallway. Is Figure 39: Hallway. Is Figure 40: Hallway. Is Back of Mallway. Is Figure 41: Hallway. Is Bedroom. Is Figure 42: Bedroom. Is Figure 43: Bedroom. Is Figure 44: Bedroom.	Figure 10:		
Figure 13: View from the lane at the rear of the property. Figure 14: View from the lane showing the rear property fence and planting.  13: Figure 15: View from the lane to the western elevation.  14: Figure 16: View showing relationship to Guildford Road.  15: Figure 17: View showing relationship to Guildford Road.  16: Figure 18: Properties on the northern side of Guildford Road.  17: Figure 19: View to buildings on the northern side of Guildford Road.  18: Figure 20: Front Elevation.  19: Figure 21: Front Elevation.  10: Figure 23: Front Elevation.  11: Figure 23: Front Elevation.  11: Figure 24: Front Elevation showing verandah.  11: Figure 25: Front Elevation showing verandah.  11: Figure 26: Rear Elevation.  12: Figure 27: Rear Elevation.  13: Figure 28: Rear Elevation.  14: Figure 29: Rear Elevation.  15: Figure 29: Rear Elevation.  16: Figure 29: Rear Elevation.  17: Figure 29: Rear Elevation.  18: Figure 30: West Elevation.  19: Figure 31: East Elevation.  10: Figure 31: East Elevation.  10: Figure 32: Remannt planting on the east side of the house.  10: Figure 33: Overgrown creeper on the west elevation.  16: Figure 35: Fence dwestern side of the lot and some remnant hardscaping.  17: Figure 36: View of the mature trees in the backyard from the lane.  18: Figure 37: Back yard.  19: Figure 38: Front Door.  10: Figure 39: Hallway.  10: Figure 40: Hallway.  11: Figure 41: Hallway.  12: Figure 42: Bedroom.  12: Figure 42: Bedroom.  13: Figure 42: Bedroom.  14: Figure 42: Bedroom.  15: Figure 42: Bedroom.  16: Figure 42: Bedroom.  17: Figure 42: Bedroom.  18: Figure 43: Bedroom.  19: Figure 44: Bedroom.  10: Figure 45: Bedroom.  10: Figure 46: Bedroom.  10: Figure 47: Bedroom.  10: Figur	Figure 11:	View of the western elevation across the adjacent vacant lots	14
Figure 14: View from the lane showing the rear property fence and planting.  Figure 15: View from the lane to the western elevation.  Figure 16: View showing relationship to Guildford Road.  Figure 17: View showing relationship to Guildford Road.  Figure 18: Properties on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing original steps.  Figure 27: Rear Elevation.  Figure 28: Recr Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 32: Remnant planting on the east side of the house.  It figure 31: Front elevation.  Figure 32: Remoded plants on the west side of the lot.  Figure 33: Frenced western side of the lot and some remnant hardscaping.  Figure 36: View of the mature frees in the backyard from the lane.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 41: Hallway.  Figure 42: Bedroom.  22: Figure 44: Bedroom.  22: Figure 44: Bedroom.	Figure 12:	View from the lane at the rear of the property.	15
Figure 15: View from the lane to the western elevation. Figure 16: View showing relationship to Guildford Road.  Figure 17: View showing relationship to Guildford Road.  Figure 18: Properties on the northern side of Guildford Road.  Figure 19: View to buildings on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing verandah.  Figure 26: Rear Elevation showing original steps.  Figure 27: Rear Elevation.  Figure 28: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 32: Remnant planting on the east side of the house.  Figure 34: Rubble and degraded plants on the west side of the lot.  Figure 35: Fenced western side of the lot and some remnant hardscaping.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 39: Hallway.  Figure 40: Hallway.  Figure 41: Hallway.  Figure 42: Bedroom.  Figure 42: Bedroom.  Figure 43: Bedroom.  22  Figure 44: Bedroom.	Figure 13:	View from the lane at the rear of the property	15
Figure 16: View showing relationship to Guildford Road.  Figure 17: View showing relationship to Guildford Road.  Figure 18: Properties on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing original steps.  Figure 26: Rear Elevation.  Figure 27: Rear Elevation.  Figure 28: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 32: Remnant planting on the east side of the house.  Figure 33: Overgrown creeper on the west elevation.  Figure 34: Rubble and degraded plants on the west side of the lot.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 39: Hallway.  Figure 40: Hallway.  Figure 41: Hallway.  Figure 42: Bedroom.  22: Figure 42: Bedroom.  22: Figure 44: Bedroom.  23: Figure 42: Bedroom.  24: Figure 42: Bedroom.  25: Figure 44: Bedroom.  26: Figure 42: Bedroom.  26: Figure 42: Bedroom.  26: Figure 42: Bedroom.  27: Figure 44: Bedroom.  28: Figure 44: Bedroom.  29: Figure 44: Bedroom.  20: Figure 44: Bedroom.  20: Figure 42: Bedroom.  20: Figure 42: Bedroom.  20: Figure 44: Bedroom.  20: Figure 44: Bedroom.  20: Figure 42: Bedroom.	Figure 14:	View from the lane showing the rear property fence and planting	15
Figure 17: View showing relationship to Guildford Road.  Figure 18: Properties on the northern side of Guildford Road.  Figure 19: View to buildings on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing original steps.  Figure 26: Rear Elevation.  Figure 27: Rear Elevation.  Figure 28: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 32: Remnant planting on the east side of the house.  Figure 34: Rubble and degraded plants on the west side of the lot.  Figure 35: Fenced western side of the lot and some remnant hardscaping.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 40: Hallway.  Figure 41: Hallway.  Figure 42: Bedroom.  22: Figure 43: Bedroom.  22: Figure 44: Bedroom.	Figure 15:	View from the lane to the western elevation	15
Figure 18: Properties on the northern side of Guildford Road.  Figure 19: View to buildings on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing original steps.  Figure 26: Rear Elevation.  Figure 27: Rear Elevation.  Figure 28: Rear Elevation.  Figure 29: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 31: East Elevation.  Figure 32: Remnant planting on the east side of the house.  Figure 33: Overgrown creeper on the west elevation.  Figure 34: Rubble and degraded plants on the west side of the lot.  Figure 36: View of the mature trees in the backyard from the lane.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 40: Hallway.  Figure 41: Hallway.  Figure 42: Bedroom.  Figure 43: Bedroom.  Figure 44: Bedroom.  20: Figure 44: Bedroom.  21: Figure 44: Bedroom.  22: Figure 44: Bedroom.  23: Figure 44: Bedroom.  24: Figure 44: Bedroom.  25: Figure 44: Bedroom.  26: Figure 44: Bedroom.  26: Figure 44: Bedroom.  27: Figure 44: Bedroom.  28: Figure 44: Bedroom.  29: Figure 44: Bedroom.  20: Figure 41: Front Elevation.  20: Figure 42: Bedro	Figure 16:		
Figure 19: View to buildings on the northern side of Guildford Road.  Figure 20: Front Elevation.  Figure 21: Front Elevation.  Figure 22: Front Elevation.  Figure 23: Front Elevation.  Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing verandah.  Figure 26: Rear Elevation showing original steps.  Figure 27: Rear Elevation.  Figure 28: Rear Elevation.  Figure 29: Rear Elevation.  Figure 30: West Elevation.  Figure 31: East Elevation.  Figure 32: Remnant planting on the east side of the house.  Figure 33: Overgrown creeper on the west elevation.  Figure 34: Rubble and degraded plants on the west side of the lot.  Figure 35: Fenced western side of the lot and some remnant hardscaping.  Figure 37: Back yard.  Figure 38: Front Door.  Figure 39: Hallway.  Figure 39: Hallway.  Figure 40: Hallway.  Figure 41: Hollway.  Figure 42: Bedroom.  Figure 43: Bedroom.  Figure 44: Bedroom.  20: Figure 44: Bedroom.  21: Figure 44: Bedroom.  22: Figure 44: Bedroom.  23: Figure 44: Bedroom.  24: Figure 44: Bedroom.  25: Figure 44: Bedroom.  26: Figure 44: Bedroom.  26: Figure 44: Bedroom.  27: Figure 44: Bedroom.  28: Figure 44: Bedroom.  29: Figure 44: Bedroom.  20: Figure 41: Figure 42: Bed	Figure 17:	View showing relationship to Guildford Road	15
Figure 20: Front Elevation	Figure 18:	Properties on the northern side of Guildford Road	16
Figure 21: Front Elevation	Figure 19:	View to buildings on the northern side of Guildford Road	16
Figure 22: Front Elevation	Figure 20:	Front Elevation	16
Figure 23: Front Elevation	Figure 21:	Front Elevation	16
Figure 24: Front Elevation showing verandah.  Figure 25: Front Elevation showing original steps	Figure 22:	Front Elevation	17
Figure 25: Front Elevation showing original steps	Figure 23:	Front Elevation	17
Figure 26: Rear Elevation	Figure 24:	Front Elevation showing verandah	17
Figure 27: Rear Elevation. 15 Figure 28: Rear Elevation. 16 Figure 29: Rear Elevation. 17 Figure 30: West Elevation. 18 Figure 31: East Elevation. 18 Figure 32: Remnant planting on the east side of the house. 18 Figure 33: Overgrown creeper on the west elevation. 18 Figure 34: Rubble and degraded plants on the west side of the lot. 19 Figure 35: Fenced western side of the lot and some remnant hardscaping. 19 Figure 36: View of the mature trees in the backyard from the lane. 19 Figure 37: Back yard. 19 Figure 38: Front Door. 20 Figure 39: Hallway. 20 Figure 40: Hallway. 20 Figure 41: Hallway. 20 Figure 42: Bedroom. 22 Figure 43: Bedroom. 22 Figure 44: Bedroom. 22 Figure 44: Bedroom. 22	Figure 25:	Front Elevation showing original steps	17
Figure 28: Rear Elevation. 18 Figure 29: Rear Elevation. 18 Figure 30: West Elevation. 18 Figure 31: East Elevation. 18 Figure 32: Remnant planting on the east side of the house 18 Figure 33: Overgrown creeper on the west elevation. 18 Figure 34: Rubble and degraded plants on the west side of the lot 19 Figure 35: Fenced western side of the lot and some remnant hardscaping. 19 Figure 36: View of the mature trees in the backyard from the lane. 19 Figure 37: Back yard. 19 Figure 38: Front Door. 20 Figure 39: Hallway. 20 Figure 40: Hallway. 20 Figure 41: Hallway. 20 Figure 42: Bedroom. 22 Figure 43: Bedroom. 22 Figure 44: Bedroom. 22 Figure 44: Bedroom. 22	Figure 26:	Rear Elevation.	17
Figure 29: Rear Elevation. 18 Figure 30: West Elevation. 18 Figure 31: East Elevation. 18 Figure 32: Remnant planting on the east side of the house. 18 Figure 33: Overgrown creeper on the west elevation. 18 Figure 34: Rubble and degraded plants on the west side of the lot. 19 Figure 35: Fenced western side of the lot and some remnant hardscaping. 19 Figure 36: View of the mature trees in the backyard from the lane. 19 Figure 37: Back yard. 19 Figure 38: Front Door. 20 Figure 39: Hallway. 20 Figure 40: Hallway. 20 Figure 41: Hallway. 20 Figure 42: Bedroom. 22 Figure 43: Bedroom. 22 Figure 44: Bedroom. 22 Figure 44: Bedroom. 22	Figure 27:	Rear Elevation.	17
Figure 30: West Elevation. 18 Figure 31: East Elevation. 18 Figure 32: Remnant planting on the east side of the house. 18 Figure 33: Overgrown creeper on the west elevation. 18 Figure 34: Rubble and degraded plants on the west side of the lot. 19 Figure 35: Fenced western side of the lot and some remnant hardscaping. 19 Figure 36: View of the mature trees in the backyard from the lane. 19 Figure 37: Back yard. 19 Figure 38: Front Door. 20 Figure 39: Hallway. 20 Figure 40: Hallway. 20 Figure 41: Hallway. 20 Figure 42: Bedroom. 22 Figure 43: Bedroom. 22 Figure 44: Bedroom. 22 Figure 44: Bedroom. 22	Figure 28:	Rear Elevation.	18
Figure 31: East Elevation	Figure 29:	Rear Elevation.	18
Figure 32: Remnant planting on the east side of the house	Figure 30:	West Elevation	18
Figure 33: Overgrown creeper on the west elevation	Figure 31:		
Figure 34: Rubble and degraded plants on the west side of the lot	Figure 32:		
Figure 35:       Fenced western side of the lot and some remnant hardscaping.       19         Figure 36:       View of the mature trees in the backyard from the lane.       19         Figure 37:       Back yard.       19         Figure 38:       Front Door.       20         Figure 39:       Hallway.       20         Figure 40:       Hallway.       20         Figure 41:       Hallway.       20         Figure 42:       Bedroom.       22         Figure 43:       Bedroom.       22         Figure 44:       Bedroom.       22         Figure 44:       Bedroom.       22	Figure 33:		
Figure 36:       View of the mature trees in the backyard from the lane.       19         Figure 37:       Back yard.       19         Figure 38:       Front Door.       20         Figure 39:       Hallway.       20         Figure 40:       Hallway.       20         Figure 41:       Hallway.       20         Figure 42:       Bedroom.       22         Figure 43:       Bedroom.       22         Figure 44:       Bedroom.       22         Figure 44:       Bedroom.       22			
Figure 37:       Back yard       19         Figure 38:       Front Door       20         Figure 39:       Hallway       20         Figure 40:       Hallway       20         Figure 41:       Hallway       20         Figure 42:       Bedroom       2         Figure 43:       Bedroom       2         Figure 44:       Bedroom       2         Figure 44:       Bedroom       2	Figure 35:	taran da antara da a	
Figure 38:       Front Door.       20         Figure 39:       Hallway.       20         Figure 40:       Hallway.       20         Figure 41:       Hallway.       20         Figure 42:       Bedroom.       20         Figure 43:       Bedroom.       21         Figure 44:       Bedroom.       22         Figure 44:       Bedroom.       22	Figure 36:		
Figure 39:       Hallway.       20         Figure 40:       Hallway.       20         Figure 41:       Hallway.       20         Figure 42:       Bedroom.       21         Figure 43:       Bedroom.       22         Figure 44:       Bedroom.       22		Back yard	19
Figure 40:       Hallway.       20         Figure 41:       Hallway.       20         Figure 42:       Bedroom.       2         Figure 43:       Bedroom.       2         Figure 44:       Bedroom.       2	•	Front Door.	20
Figure 41:       Hallway.       20         Figure 42:       Bedroom.       2         Figure 43:       Bedroom.       2         Figure 44:       Bedroom.       2		,	
Figure 42:         Bedroom         2           Figure 43:         Bedroom         2           Figure 44:         Bedroom         2		·	
Figure 43:         Bedroom.         2           Figure 44:         Bedroom.         2	•	Hallway.	20
Figure 44: Bedroom	Figure 42:		
	-	Bedroom.	21
Figure 45: Redroom 1	-	Bedroom	21
<del>-</del>	Figure 45:	Bedroom 1.	21
Figure 46: Bedroom 1	-		
Figure 47: Detail of floorboards	-		
Figure 48: Bedroom 2	-		
Figure 49: Bedroom 3			
Figure 50: Lounge Room	-		
Figure 51: Lounge Room	•		
Figure 52: Lounge Room			
Figure 53: Lounge Room			
Figure 54: Dining Room (former kitchen)	Figure 54:	Dining Room (former kitchen)	23



Figure 55:	Dining Room (former kitchen)	23
Figure 56:	Kitchen	
Figure 57:	Kitchen ceiling	24
Figure 58:	Kitchen alcove	24
Figure 59:	Kitchen	24
Figure 60:	Sleepout looking through to Dining Room	25
Figure 61:	Sleepout looking through to Dining Room.	
Figure 62:	Bathroom door and ceiling.	
Figure 63:	Bathroom	
Figure 64:	Bathroom.	
Figure 65:	Bathroom window.	



## 1.0 Background

This photograph archival record has been prepared at the request of the Department of Planning Lands and Heritage. Demolition is proposed for the building to enable future development of this site and adjacent properties on Guildford Road and East Parade, Mount Lawley.

This place was considered by the Department of Planning Lands and Heritage for inclusion in the State Register of Heritage Places in 2002 and was found to be below threshold for inclusion.

The place has been identified by the City of Vincent as a Moderate Level of Significance which is described as:

Contributes to the heritage of the locality. Has some altered or modified elements, not necessarily detracting from the overall significance of the place.

Management Category B - Conservation Recommended

Consider for inclusion on the MHI (Heritage List) if owner/applicant consents to inclusion.

This Archival Record has been prepared to enable the development of the site whilst recognising the heritage values of the place.

## 2.0 Statement of Significance

The City of Vincent have prepared the following statement.

The house at 40 Guildford Road is a substantial and good example of the Federation Arts and Crafts style, which demonstrates the aspirations of the original developers for this neighbourhood before the growth of traffic on Guildford Road impacted so heavily on amenity.

### 3.0 Location

The property is located on the south east side of Guildford Road in the block bound by Stanley Street and East Parade.

The property is located across two lots; lot 254 (40) on Plan 2001 and lot 403 on Deposited Plan 31182 as designated on Certificate of Title Volume 2209 Folio 50.

On either side of the lot are vacant lots where former residences of a similar age were located.






Figure 1: Location Plan

#### COURTESY NEARMAP



Figure 2: Lots 254 and 403 (40) Guildford Road Mount Lawley.

#### COURTESY CITY OF VINCENT INTRAMAPS






Figure 3: Site Plan



## 4.0 Brief History

This history has been expanded from the research prepared for the City of Vincent Local Heritage Survey. Acknowledgement is extended to the authors of that documentation.

This section of Guildford Road is part of the East Norwood Estate which was developed in 1898, on part of Locations A4 and A5, on the eastern side of the Fremantle-Guildford Railway line, in the East Perth/Mt Lawley area. The subdivision was carried out by surveyors Crossland & Hardy on behalf of the Perth (WA) Estate Company Limited of 364 Hay Street.

The strong demand for new housing was a result of the population boom created by the gold discoveries in the State. One member of the Perth (WA) Estate Company was Zebina Lane, who was an engineer and mine owner at the Great Boulder mines, and one of a number of people who made money in gold mining and reinvested it in land developments during this period. The Company had previously developed the adjoining Westralia Estate on the west side of the railway line on Location A4. The estate was promoted as having 'splendid building lots', 'made roads' and 'river frontages'. In the latter case these were the larger blocks along Joel Terrace which were expected to attract the wealthier buyers. It is evident from the subdivision map that this was not one of the earliest blocks sold, the earliest being those used for 'spec' and rental housing along the railway line (East Parade), Bramall and Summers Street.

The estate's boundary nearest to the subject place was Stanley Street (two house blocks from No. 40), which later became the boundary between the Town of Vincent (formed 1995) and that portion of Mount Lawley which is in the City of Stirling. This section of Guildford Road was listed in the Wise's Post Office Directories initially as 'Guildford old road' and by 1905 it was known as 'Old Guildford Road' and listed in conjunction with Lord Street. Around 1908 it became known as 'Guildford Road, Norwood' and it remained so until the 1940's.

No 40 Guildford Road, was well positioned for access to Perth's train system via the nearby Mount Lawley Station. Then in 1924 a single tram track was laid from the tram terminus on the corner of Lord and Lincoln Streets through the Mount Lawley Subway to Maylands. In 1939 this line was duplicated, and the Subway widened to accommodate the second track. This further improved access to the city.

In 1925 the resident was Herbert Illingworth. At that time the area around the Mount Lawley Subway (just a street block away) was a thriving village. The shops and businesses also listed in the Directories were No. 1 Guildford Road Methodist Church, No. 3 plumber, No. 5 Laundry, Nos. 8 - 10 butcher, No. 12 fancy goods and draper, No. 14 confectioner and grocer, No. 15 newsagent, stationer, tobacconist and State Savings Bank agency, No. 18 tobacco and fancy goods and No. 19 butcher. In 1.

The subdivision plan for this property was approved in 1898 and lots were purchased from the developer British Westralia Syndicate Limited.<sup>2</sup> Lots 253 and 254 were purchased in 1902 by Alice Victoria McColl.<sup>3</sup>

Alice Victoria McColl (c1863-1914) was the wife of railway employee, Stawell Austral McColl (c1861-1916). From the available evidence in the Post Office Directories and Electoral Rolls the place was built in 1904 as A. McColl is recorded living in Guildford Road in 1905. The builder or architect of the residence has not been determined. It is likely that a local builder, such as John Berne Hawkins who lived in Guildford Road, constructed the home in accordance with readily available plans from pattern books that were in common usage at the time. The plan form and remaining detail of the building indicate that the home was of some quality and not a cottage for occupants of limited

<sup>&</sup>lt;sup>3</sup> Certificate of Title, 161/20, Landgate.



9

Place 3818 House, City of Vincent InHerit database entry. Adopted 2006.

<sup>&</sup>lt;sup>2</sup> Certificate of Title, 161/20, Landgate.

income. This conclusion is also supported by the evidence that the residence occupied more than one lot it and was set in a more expansive garden setting.<sup>4</sup>




Figure 4: Sewerage Plan Sheet 226, 1917.

COURTESY SROWA SERIES 634 CONS 4156 ITEM 0226

The McColls appear to have lived in the place until c1911 and subsequently leased the place to tenants. A newspaper article from March 1911 records that Stawell and Alice McColl were living in St Georges Terrace Perth at that time.<sup>5</sup>

Post Office Directories record that there was a rapid turnover of occupants between 1912 and 1915 and was then occupied by caterer Andrew Cavanagh and his wife Jane until 1918.

In 1914, Alice McColl died, and the property transferred to Stawell McColl, and on his death in 1916 the property was transferred to their children, Alice Sophia McColl and Archibald Dougald McColl.<sup>6</sup> The siblings continued to lease the property to tenants, traveller Herbert Illingworth and his wife Ethel Illingworth from 1919 to 1926.<sup>7</sup>

In 1926, the property was transferred to clerk Frederick William James Joyce (c1893-1973) and his wife Eunice Hilda Joyce, nee Bevan (c1895-1977). The couple married in 1914 and had at least four children and lived at this house until the 1970s. Frederick Joyce died in 1973 and Eunice lived on in the house until at least 1975 when the place was transferred to draftsman William Richard Marks and

Post Office Directories, State Library of WA, <u>Post office directories | State Library of Western Australia</u> (slwa.wa.gov.au) accessed February 2023.



10

Sewerage Plan Sheet 226 shows the width of the lot is larger than the majority of the housing lots adjacent.

The West Australian, 29 March 1911, p. 4.

<sup>6</sup> Certificates of Title, 682/184 and 682/185, Landgate.

Public Relations Officer Lynette Marks.<sup>8</sup> The couple lived at the house until 1986 when the house was transferred to the Western Australian Planning Commission.<sup>9</sup> With the transfer of the property to the WAPC the residence was leased to tenants.

Aerial photographs from the mid 20<sup>th</sup> century indicate that the extent and form of the residence have not changed considerably since that time. The WAPC and its subsequent authorities maintained the property when it was occupied by tenants including the replacement of the roof cladding in the late 1980s.

The physical evidence suggests that the timber verandah was replaced in the late 1980s with the current verandah which is brick laid on sand.

The houses located to the south of the 40 Guildford Road were demolished in 2000, and the house to the north was demolished c2009. The original residential context of this portion of Guildford Road has been lost as a result of these changes.

The residence has been unoccupied for several years and is in a very poor condition.

#### 4.1 Occupants and owners


DATE	OWNERS	OCCUPANT
1898 - 1902	British Westralia Syndicate Limited	None
1902 - 1918	Alice Victoria McColl	<ul> <li>1905 – 1911 Stawell Austral McColl and Alice Victoria McColl.</li> <li>1912 William J Franz</li> <li>1913 Frederick W Koeppe</li> <li>1914 John Dillon and Haswell Bromley</li> <li>1915 - 1918 Andrew and Jane Cavanagh</li> </ul>
1918 - 1926	Alice Sophia McColl and Archibald Dougald McColl	1919 - 1926 Herbert Illingworth
1926 – 1975	Frederick William Joyce and Eunice Hilda Joyce.	Frederick William Joyce (until 1973) and Eunice Hilda Joyce.
1975 - 1986	William Richard Marks and Theresa Barbara Marks	William Richard Marks and Theresa Barbara Marks
1986 - 2001	Western Australian Planning Commission	Various
2001 – 2023	Western Australian Planning Commission (Dept of Planning Lands and Heritage)	Various and vacant


<sup>&</sup>lt;sup>9</sup> Certificate of Title 1070/301, Landgate.



11

<sup>8</sup> Certificate of Title 1033/111, Landgate.








Figure 7: Floor Plan



## 5.0 Photographs

The following images were taken on 8 March 2023 by Hocking Heritage + Architecture. No access was available to the roof space or underfloor space.

### 5.1 Streetscape



Figure 8: View southwest on Guildford Road and vacant lot adjacent.



Figure 9: View southwest on Guildford Road towards the Mount Lawley subway.



Figure 10: View northeast on Guildford Road towards subject property.



Figure 11: View of the western elevation across the adjacent vacant lots.



Figure 12: View from the lane at the rear of the property.



Figure 13: View from the lane at the rear of the property.



Figure 14: View from the lane showing the rear property fence and planting.



Figure 15: View from the lane to the western elevation.



Figure 16: View showing relationship to Guildford Road.



Figure 17: View showing relationship to Guildford Road.



Figure 18: Properties on the northern side of Guildford Road.



Figure 19: View to buildings on the northern side of Guildford Road.

#### 5.2 Elevations and Landscape

The majority of the exterior of the original residence still demonstrates the brick construction with concrete bands and some remnants of tuckpointing. Large areas of the external walls have graffiti and the surrounding grounds are in poor condition although there are some mature trees.



Figure 20: Front Elevation



Figure 21: Front Elevation



Figure 22: Front Elevation.



Figure 23: Front Elevation.



Figure 24: Front Elevation showing verandah.



Figure 25: Front Elevation showing original steps.



Figure 26: Rear Elevation.



Figure 27: Rear Elevation.





Figure 28: Rear Elevation.



Figure 29: Rear Elevation.



Figure 30: West Elevation.



Figure 31: East Elevation.



Figure 32: Remnant planting on the east side of the house



Figure 33: Overgrown creeper on the west elevation.



Figure 34: Rubble and degraded plants on the west side of the lot.



Figure 35: Fenced western side of the lot and some remnant hardscaping.



Figure 36: View of the mature trees in the backyard from the lane.



Figure 37: Back yard.

### 5.3 Internal Photographs

The interior of the property was poorly lit and difficult to navigate because of the removed floorboards and accumulation of debris. The following photographs demonstrate that the majority of detail has been removed. Apart from some original floorboards there are no architraves, skirtings or doors. There is also asbestos sheeting in the rear of the building.



Figure 38: Front Door.



Figure 39: Hallway.



Figure 40: Hallway.



Figure 41: Hallway.





Figure 42: Bedroom



Figure 43: Bedroom.



Figure 44: Bedroom



Figure 45: Bedroom 1.



Figure 46: Bedroom 1.



Figure 47: Detail of floorboards.





Figure 48: Bedroom 2.



Figure 49: Bedroom 3.



Figure 50: Lounge Room.



Figure 51: Lounge Room.




Figure 52: Lounge Room




Figure 53: Lounge Room



Figure 54: Dining Room (former kitchen)



Figure 55: Dining Room (former kitchen)







Figure 57: Kitchen ceiling.



Figure 58: Kitchen alcove.




Figure 59: Kitchen.



Figure 60: Sleepout looking through to Dining Room.



Figure 61: Sleepout looking through to Dining Room.



Figure 62: Bathroom door and ceiling.



Figure 63: Bathroom.



Figure 64: Bathroom.



Figure 65: Bathroom window.



Your ref: DA5.2023.176.1 Our ref: A13337550

Enquiries: Blake Rawlinson 6551 8191

blake.rawlinson@dplh.wa.gov.au

David MacLennan
Chief Executive Officer
City of Vincent
Via email to: mail@vincent.wa.gov.au

Dear Mr MacLennan

## RESPONSE TO COUNCIL RESOLUTION - AMENDMENT TO THE MUNICIPAL HERITAGE INVENTORY: 40 GUILDFORD ROAD, MOUNT LAWLEY

At its ordinary council meeting on 17 October 2023, the City of Vincent Council considered an item (item 9.2) submitted by the Department of Planning, Lands and Heritage (DPLH) for the amendment of the Municipal Heritage Inventory to remove the place located at Lots 254 & 403 (No.40) Guildford Road, Mount Lawley from the inventory.

#### Council resolved the following:

'That the motion be deferred to seek further advice from the Department of Planning, Lands and Heritage and Main Roads WA regarding the justification for widening in this particular location, supported by traffic studies, applicable standards and potentially requesting some level of detailed design around what is proposed in this area that would necessitate demolition of this structure.'

DPLH provides the following information in response to the Council's resolution:

#### Traffic Study and Road Widening Requirement

DPLH has been in consultation with Main Roads WA (MRWA) regarding the proposed road widening along Guildford Road required for the purpose of future upgrades to the intersection of Guildford Road and East Parade.

DPLH requested MRWA to provide any available traffic studies, standards, and concept designs forming the rationale for the land take requirements on Guildford Road impacting Lots 254 and 403. MRWA provided the attached Traffic Assessment Report which details the traffic study undertaken and the analysis and applicable standards applied in determining the road widening requirements.

The key findings of the report are summarised as follows:

- The current movement from Guildford Road turning left into East Parade is significant and the proposed intersection upgrade concept design includes double left turning lanes under traffic signal control.
- Traffic impacts under the current intersection concept design sit just within the
  desirable level of service limits and shortening the length of the left turning lanes
  would have a negative impact on service at the intersection particularly on queuing of
  through traffic in the central lanes.

- Given the significant left turn movements the current proposed length of the turning lanes need to be maintained to ensure that vehicles do not queue into the through lanes on Guildford Road creating traffic safety issues or exacerbating congestion.
- On this basis, the road widening land take requirement impacting Lots 254 and 403
  Guildford Road is necessary to ensure acceptable traffic impacts and level of service
  can be maintained at the Guildford Road / East Parade intersection into the future.

#### **Detailed Design**

MRWA have advised that the intersection upgrade is yet to progress through the project development phase which includes development of detailed road designs and road sections. As such, at this time, there are no detailed designs or road design cross sections available for dissemination. Once the project development phase progresses, MRWA will undertake further consultation with the City of Vincent to resolve the detailed designs.

The authorised MRWA Land Dealings Plan dated 5 September 2023 is the most accurate plan currently available which delineates the extent of road widening required to accommodate the current intersection upgrade design based on the preferred design scenarios tested in the Traffic Impact Assessment.

DPLH requests the City of Vincent accepts this letter and its attachments as its formal response to the Council resolution in support of our application for the removal of No. 40 Guildford Road from the City's Municipal Heritage Inventory. DPLH respectfully requests that the City submits this response in support of the application to Council for consideration at the next available Council meeting in order to have the item determined.

Should you have any queries, please contact Blake Rawlinson, Senior Project Officer on telephone 6551 8191 or via email to blake.rawlinson@dplh.wa.gov.au.

Yours sincerely

Scott McGill

Director Housing Diversity Pipeline

1 March 2024

Att. Traffic Assessment Report -Guildford Road to East Parade Left Turn Assessment





We're working for Western Australia.

## **Traffic Assessment Report**

Guildford Road to East Parade Left Turn Assessment

## Contents

1	SCOPE	4
2	SCENARIOS	5
3	MODEL ASSUMPTIONS & CALIBRATION	5
4	ASSESSMENT – EXISTING LAYOUT	6
4.1	Model Layout – Guildford Road & East Parade & Whatley Crescent	6
4.2	Modelling Results – 2021 Traffic Volumes	7
4.3	Modelling Results – 2026 Traffic Volumes	8
5	ASSESSMENT – OPTION 2A	9
5.1	Model Layout – Guildford Road & East Parade & Whatley Crescent	9
5.2	Modelling Results – 2031 Traffic Volumes	10
5.3	Modelling Results – 2036 Traffic Volumes	11
6	COMMENTARY	12

# **Report Details**

Project Manager:	Gary Manning – Project Development
Description:	Guildford Road to East Parade Left Turn Assessment
RTE Reference:	T23018
Analysed by:	Timothy Wong, Traffic Engineer, Road & Traffic Engineering Branch
Reviewed by:	Raj Shah, Senior Traffic Engineer, Road & Traffic Engineering Branch
Issue Date:	22 January 2024
Software Version:	SIDRA Intersection, Ver 9.1.4.221

## **Amendments**

Revision Number	Revision Date	Description of Key Changes	Section / Page No.
0	22/01/2024	Report Issued	All
1	5/02/2024	Minor commentary changes	All
2	2/04/2024	Existing Layout 2021 results added	All

Document No: D24#151441 Page 3 of 14

#### 1 SCOPE

The Project Development branch has requested Road & Traffic Engineering (RTE) to undertake a comparative SIDRA analysis of the existing Guildford Road to East Parade single left turn pocket (shown in Figure 1 below) as compared to the dual left turn pockets in the proposed layout (labelled Option 2a in this report). The intent of this analysis is to assess the optimum length for the left turn pockets in the proposed Option 2a layout at various timeframes.



Figure 1: Guildford Rd & East Parade & Whatley Crescent. Source: ImageNow 2023

Document No: D24#151441 Page 4 of 14

#### 2 SCENARIOS

Table 1 details the models and options of Guildford Road & East Parade & Whatley Crescent intersection that have been assessed. Traffic volumes used in the models have been provided by the Project Manager for direct input into the models. The URP method has been used to calibrate the ROM volumes.

Table 1: Models and Options

Model	Description
Existing Layout	Existing Layout and Configuration (2021, 2026)
Option 2a	<ul> <li>Layout as provided by the Project Manager in the Modelling Scope (2031, 2036)</li> </ul>

#### 3 MODEL ASSUMPTIONS & CALIBRATION

The following lists outlines the assumptions and calibration used for the SIDRA traffic models:

- Forecast traffic volumes have been calibrated with 2021 ROM24 base volumes, and projected to 2031 and 2036 based on the URP method.
- In the absence of saturation flow data obtained from the site, conservative values ranging from 1800 pcu/hr/lane to 1950 pcu/hr/lane have been assumed.
- Where there are pedestrian crossings, a value of 20 peds/hr has been assumed.
- For Option 2a, there is no current volume data for the South approach right turn movement
  as the movement is currently banned. The 2021 volumes for the right turn volume have
  been calculated by using the same ratio of East approach left turn volume to ROM volume
  in the alternate peak period (ie. AM peak ratio has been used in determining the PM peak
  ratio for the banned right turn movement). The right turn volumes on the South approach
  are then subtracted from the through volumes.

Document No: D24#151441 Page 5 of 14

### 4 ASSESSMENT – EXISTING LAYOUT

### 4.1 Model Layout - Guildford Road & East Parade & Whatley Crescent




Figure 2: Existing layout and phasing from SIDRA

Document No: D24#151441 Page 6 of 14

### 4.2 Modelling Results – 2021 Traffic Volumes

## Site: G-E/W [AM 2021 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Existing Layout)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

NA
Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 90 seconds (Site User-Given Cycle Time)

Vehicle	Movem	nent Perfo	rmance												
Mov ID	Turn	Mov Class	Demand [ Total	Flows HV]	Arrival [ Total	Flows HV]	Deg. Satn	Aver. Delay	Level of Service	95% Back [ Veh.	Of Queue Dist ]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver. Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m			,	km/h
South: E	East Pde														
1	L2	All MCs	368	1.4	368	1.4	1.016	73.5	LOSE	37.4	282.0	1.00	1.24	1.47	22.2
2	T1	All MCs	854	3.2	854	3.2	1.016	67.7	LOSE	38.1	290.2	1.00	1.28	1.47	28.3
Approac	ch		1222	2.7	1222	2.7	1.016	69.4	LOSE	38.1	290.2	1.00	1.27	1.47	26.6
East: Gu	uilford Rd														
4	L2	All MCs	953	1.3	953	1.3	* 1.064	83.3	LOSF	63.1	470.7	1.00	1.22	1.55	25.4
5	T1	All MCs	1344	2.7	1344	2.7	0.652	17.2	LOS B	20.7	157.2	0.76	0.69	0.76	44.1
Approac	ch		2297	2.2	2297	2.2	1.064	44.6	LOS D	63.1	470.7	0.86	0.91	1.09	31.4
North: V	Vhatley C	res													
8	T1	All MCs	1285	1.6	1285	1.6	* 1.039	74.2	LOSE	40.7	303.7	1.00	1.35	1.52	27.1
Approac	ch		1285	1.6	1285	1.6	1.039	74.2	LOS E	40.7	303.7	1.00	1.35	1.52	27.1
West: G	uilford Ro	t													
10	L2	All MCs	52	2.0	52	2.0	0.419	19.1	LOS B	11.0	83.4	0.63	0.58	0.63	43.0
11	T1	All MCs	804	3.4	804	3.4	0.419	12.9	LOS B	11.1	84.1	0.63	0.57	0.63	45.9
Approac	ch		856	3.3	856	3.3	0.419	13.3	LOS B	11.1	84.1	0.63	0.57	0.63	45.7
All Vehic	cles		5660	2.3	5660	2.3	1.064	52.0	LOS D	63.1	470.7	0.89	1.03	1.20	30.1

## Site: G-E/W [PM 2021 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Existing Layout)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

NA
Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 120 seconds (Site User-Given Cycle Time)

Vehicle	Movem	ent Perfo	rmance												
Mov ID	Turn	Mov Class	Demand [ Total	Flows HV]	Arrival [ Total	Flows HV]	Deg. Satn	Aver. Delay	Level of Service	95% Back [ Veh.	Of Queue Dist ]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver. Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m				km/h
South: E	East Pde														
1	L2	All MCs	284	0.0	284	0.0	0.995	58.6	LOSE	80.2	594.2	1.00	1.15	1.22	26.0
2	T1	All MCs	1945	1.0	1945	1.0	* 0.995	52.9	LOS D	80.9	600.9	1.00	1.16	1.22	32.0
Approac	ch		2229	8.0	2229	8.0	0.995	53.6	LOS D	80.9	600.9	1.00	1.16	1.22	31.3
East: G	uilford Rd														
4	L2	All MCs	483	1.3	483	1.3	0.856	54.1	LOS D	29.0	216.2	1.00	0.93	1.11	30.9
5	T1	All MCs	597	1.8	597	1.8	0.493	35.6	LOS D	14.1	105.8	0.86	0.74	0.86	32.8
Approac	ch		1080	1.6	1080	1.6	0.856	43.9	LOS D	29.0	216.2	0.92	0.82	0.97	31.8
North: V	Vhatley C	res													
8	T1	All MCs	796	1.6	796	1.6	0.356	13.9	LOS B	12.0	90.1	0.56	0.50	0.56	48.9
Approac	ch		796	1.6	796	1.6	0.356	13.9	LOS B	12.0	90.1	0.56	0.50	0.56	48.9
West: G	Builford Ro	t													
10	L2	All MCs	92	0.0	92	0.0	1.000	80.9	LOSF	45.1	338.2	1.00	1.19	1.32	21.3
11	T1	All MCs	1112	2.3	1112	2.3	* 1.000	74.3	LOSE	45.4	341.6	1.00	1.20	1.32	21.9
Approac	ch		1203	2.1	1203	2.1	1.000	74.8	LOSE	45.4	341.6	1.00	1.20	1.32	21.9
All Vehic	cles		5308	1.4	5308	1.4	1.000	50.5	LOS D	80.9	600.9	0.92	1.00	1.09	30.9

Page 7 of 14 Document No: D24#151441

### 4.3 Modelling Results – 2026 Traffic Volumes

#### Site: G-E/W [AM 2026 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Existing Layout)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

NA
Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 80 seconds (Site User-Given Cycle Time)

Vehicle	Mover	nent Perfo	ormance												
Mov ID	Turn	Mov Class	Demand F [ Total	HV]	Arrival F [ Total	HV]	Deg. Satn	Aver. Delay	Level of Service	[ Veh.	Of Queue Dist ]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver. Speed
South: E	ast Pde		veh/h	%	veh/h	%	v/c	sec		veh	m				km/h
1	L2	All MCs	396	1.4	396	1.4	1.125	107.5	LOS F	43.1	324.3	1.00	1.47	1.88	17.2
2	T1	All MCs	917	3.2	917	3.2	1.125	101.7	LOS F	43.9	334.0	1.00	1.54	1.87	22.4
Approac	h		1313	2.7	1313	2.7	1.125	103.5	LOS F	43.9	334.0	1.00	1.52	1.88	20.9
East: Gu	uilford Ro	d													
4	L2	All MCs	1098	1.3	1098	1.3	<b>*</b> 1.186	130.0	LOS F	79.7	594.0	1.00	1.42	2.03	19.5
5	T1	All MCs	1549	2.7	1549	2.7	0.761	19.2	LOS B	24.0	181.6	0.84	0.78	0.85	43.7
Approac	:h		2647	2.1	2647	2.1	1.186	65.1	LOSE	79.7	594.0	0.91	1.04	1.34	25.9
North: V	Vhatley (	Cres													
8	T1	All MCs	1397	1.6	1397	1.6	* 1.164	117.2	LOS F	48.8	364.5	1.00	1.65	2.00	20.6
Approac	h		1397	1.6	1397	1.6	1.164	117.2	LOSF	48.8	364.5	1.00	1.65	2.00	20.6
West: G	uilford R	ld													
10	L2	All MCs	58	2.0	58	2.0	0.475	18.5	LOS B	11.5	87.8	0.67	0.61	0.67	43.4
11	T1	All MCs	900	3.4	900	3.4	0.475	12.3	LOS B	11.6	88.5	0.67	0.60	0.67	46.4
Approac	:h		958	3.3	958	3.3	0.475	12.7	LOS B	11.6	88.5	0.67	0.60	0.67	46.2
All Vehic	cles		6315	2.3	6315	2.3	1.186	76.6	LOSE	79.7	594.0	0.91	1.21	1.50	24.3

## Site: G-E/W [PM 2026 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Existing

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

		nent Perf													
Mov ID	Turn	Mov Class	Demand [ Total		Arrival I [ Total	Flows HV]	Deg. Satn	Aver. Delay	Level of Service	95% Back [ Veh.	Of Queue Dist ]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver. Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m				km/h
South: E	East Pde														
1	L2	All MCs	305	0.0	305	0.0	1.080	88.9	LOS F	99.3	735.4	1.00	1.27	1.38	19.9
2	T1	All MCs	2088	1.0	2088	1.0	* 1.080	83.2	LOS F	100.2	743.9	1.00	1.29	1.38	25.3
Approac	ch		2394	0.9	2394	0.9	1.080	84.0	LOSF	100.2	743.9	1.00	1.29	1.38	24.7
East: G	uilford Ro	d													
4	L2	All MCs	557	1.3	557	1.3	0.945	69.8	LOS E	40.7	302.9	1.00	1.02	1.20	27.3
5	T1	All MCs	688	1.8	688	1.8	0.544	38.1	LOS D	17.7	133.0	0.87	0.75	0.87	31.9
Approac	ch		1245	1.6	1245	1.6	0.945	52.3	LOS D	40.7	302.9	0.93	0.87	1.02	29.2
North: V	Vhatley C	Cres													
8	T1	All MCs	865	1.6	865	1.6	0.392	15.9	LOS B	14.7	110.2	0.59	0.52	0.59	47.7
Approac	ch		865	1.6	865	1.6	0.392	15.9	LOS B	14.7	110.2	0.59	0.52	0.59	47.7
West: G	uilford R	d													
10	L2	All MCs	103	0.0	103	0.0	1.071	105.9	LOSF	56.5	423.8	1.00	1.28	1.42	17.7
11	T1	All MCs	1243	2.3	1243	2.3	* 1.071	99.3	LOS F	56.9	427.9	1.00	1.29	1.42	18.1
Approac	ch		1346	2.1	1346	2.1	1.071	99.8	LOSF	56.9	427.9	1.00	1.29	1.42	18.1
All Vehic	cles		5851	1.4	5851	1.4	1.080	70.8	LOSE	100.2	743.9	0.92	1.09	1.20	25.9

Document No: D24#151441 Page 8 of 14

### 5 ASSESSMENT – OPTION 2A

### 5.1 Model Layout – Guildford Road & East Parade & Whatley Crescent




Figure 3: Option 2a layout and phasing from SIDRA

Document No: D24#151441 Page 9 of 14

### 5.2 Modelling Results – 2031 Traffic Volumes

#### Site: G-E/W [AM 2031 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Option 2a)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 100 seconds (Site User-Given Cycle Time)

Vehicle	e Mover	nent Perf	ormance												
Mov ID	Turn	Mov Class	Demand [ Total		Arrival [ Total	Flows HV]	Deg. Satn	Aver. Delay	Level of Service	95% Back [ Veh.	Of Queue Dist ]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver. Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m			0,000	km/h
South:	East Pde	:													
1	L2	All MCs	388	1.4	388	1.4	0.444	24.0	LOS C	12.4	93.1	0.71	0.78	0.71	37.3
2	T1	All MCs	238	8.4	238	8.4	0.278	16.6	LOS B	6.9	55.7	0.64	0.54	0.64	47.2
3	R2	All MCs	662	1.3	662	1.3	*1.064	99.3	LOS F	23.0	171.6	1.00	1.20	1.62	22.6
Approa			1288	2.7	1288	2.7	1.064	61.4	LOSE	23.0	171.6	0.85	0.95	1.16	28.2
East: G	uilford R	d													
4	L2	All MCs	1134	1.3	1134	1.3	0.628	21.2	LOS C	21.4	159.8	0.62	0.77	0.62	45.3
5	T1	All MCs	1599	2.7	1599	2.7	<b>*</b> 1.055	80.7	LOS F	55.5	420.6	1.00	1.37	1.49	21.3
Approa	ch		2733	2.2	2733	2.2	1.055	56.0	LOSE	55.5	420.6	0.84	1.12	1.13	28.6
North: \	Whatley (	Cres													
8	T1	All MCs	1285	1.6	1285	1.6	* 1.030	70.7	LOS E	33.3	248.6	0.99	1.16	1.36	28.2
Approa	ch		1285	1.6	1285	1.6	1.030	70.7	LOSE	33.3	248.6	0.99	1.16	1.36	28.2
West: 0	Builford R	Rd													
10	L2	All MCs	54	2.0	54	2.0	0.584	31.6	LOS C	16.7	126.9	0.84	0.75	0.84	35.8
11	T1	All MCs	823	3.4	823	3.4	0.584	25.2	LOSC	16.8	128.0	0.84	0.74	0.84	37.8
Approa	ch		877	3.3	877	3.3	0.584	25.6	LOS C	16.8	128.0	0.84	0.74	0.84	37.7
All Vehi	icles		6183	2.3	6183	2.3	1.064	55.9	LOSE	55.5	420.6	0.87	1.04	1.14	29.2

#### Site: G-E/W [PM 2031 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Option 2a)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

NA
Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 110 seconds (Site User-Given Cycle Time)

Mov	Turn	Mov	Demand I		Arrival I		Deg.	Aver.	Level of		Of Queue	Prop.	Eff.	Aver.	Aver.
ID		Class	[ Total	HV]	[ Total	HV]	Satn	Delay	Service	[ Veh.	Dist ]	Que	Stop Rate	No. of Cycles	Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m			0,000	km/h
South: E	East Pde														
1	L2	All MCs	300	0.0	300	0.0	0.282	18.3	LOS B	8.1	59.3	0.54	0.72	0.54	40.7
2	T1	All MCs	745	0.6	745	0.6	0.671	17.3	LOS B	27.4	202.7	0.75	0.69	0.75	46.8
3	R2	All MCs	1306	1.3	1306	1.3	* 1.006	76.4	LOSE	46.4	345.8	1.00	1.14	1.35	26.3
Approac	ch		2352	0.9	2352	0.9	1.006	50.3	LOS D	46.4	345.8	0.86	0.94	1.06	32.0
East: G	uilford Ro	t													
4	L2	All MCs	575	1.3	575	1.3	0.275	11.4	LOS B	6.7	49.7	0.36	0.67	0.36	48.9
5	T1	All MCs	711	1.8	711	1.8	0.584	33.9	LOSC	16.0	119.9	0.89	0.77	0.89	33.8
Approac	ch		1285	1.6	1285	1.6	0.584	23.8	LOS C	16.0	119.9	0.66	0.72	0.66	40.5
North: V	Vhatley C	Cres													
8	T1	All MCs	796	1.6	796	1.6	*0.978	67.4	LOS E	20.7	154.9	0.99	1.05	1.29	28.7
Approac	ch		796	1.6	796	1.6	0.978	67.4	LOSE	20.7	154.9	0.99	1.05	1.29	28.7
West: G	uilford R	d													
10	L2	All MCs	95	0.0	95	0.0	1.020	82.8	LOSF	44.0	329.7	1.00	1.25	1.39	21.2
11	T1	All MCs	1138	2.3	1138	2.3	* 1.020	76.2	LOSE	44.3	333.1	1.00	1.26	1.39	21.8
Approac	ch		1233	2.1	1233	2.1	1.020	76.7	LOSE	44.3	333.1	1.00	1.26	1.39	21.7
All Vehi	eles		5665	1.4	5665	1.4	1.020	52.4	LOS D	46.4	345.8	0.86	0.98	1.07	30.3

Document No: D24#151441 Page 10 of 14

#### **Modelling Results – 2036 Traffic Volumes** 5.3

#### Site: G-E/W [AM 2036 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Option 2a)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

NA
Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 110 seconds (Site User-Given Cycle Time)

Vehicle	Mover	nent Perf	ormance					_					_	_	
Mov ID	Turn	Mov Class	Demand [ Total		Arrival I [ Total	Flows HV]	Deg. Satn	Aver. Delay	Level of Service	95% Back [ Veh.	Of Queue Dist ]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m				km/h
South: E	East Pde														
1	L2	All MCs	408	1.4	408	1.4	0.465	25.9	LOS C	14.5	108.5	0.72	0.79	0.72	36.3
2	T1	All MCs	249	8.4	249	8.4	0.290	18.3	LOS B	8.0	64.3	0.64	0.55	0.64	46.3
3	R2	All MCs	697	1.3	697	1.3	* 1.102	117.8	LOSF	27.0	200.9	1.00	1.21	1.65	20.3
Approac	ch		1355	2.7	1355	2.7	1.102	71.8	LOSE	27.0	200.9	0.85	0.96	1.18	25.9
East: G	uilford R	d													
4	L2	All MCs	1185	1.3	1185	1.3	0.649	25.6	LOS C	24.8	185.1	0.62	0.77	0.62	44.7
5	T1	All MCs	1672	2.7	1672	2.7	<b>*</b> 1.100	101.0	LOSF	66.0	500.2	1.00	1.42	1.55	18.5
Approac	ch		2857	2.2	2857	2.2	1.100	69.8	LOS E	66.0	500.2	0.84	1.15	1.17	25.5
North: V	Vhatley (	Cres													
8	T1	All MCs	1394	1.6	1394	1.6	<b>*</b> 1.097	93.2	LOSF	41.3	308.8	0.99	1.24	1.44	24.2
Approac	ch		1394	1.6	1394	1.6	1.097	93.2	LOS F	41.3	308.8	0.99	1.24	1.44	24.2
West: G	uilford R	ld.													
10	L2	All MCs	59	2.0	59	2.0	0.626	34.0	LOSC	20.3	154.9	0.85	0.76	0.85	34.7
11	T1	All MCs	903	3.4	903	3.4	0.626	27.6	LOS C	20.5	156.2	0.85	0.76	0.85	36.6
Approac	ch		962	3.3	962	3.3	0.626	28.0	LOS C	20.5	156.2	0.85	0.76	0.85	36.4
All Vehic	cles		6567	2.3	6567	2.3	1.102	69.0	LOSE	66.0	500.2	0.88	1.07	1.18	26.2

#### Site: G-E/W [PM 2036 - Guilford Rd & East Pde/Whatley Cres (Site Folder: Option 2a)]

Output produced by SIDRA INTERSECTION Version: 9.1.4.221

NA
Site Category: NA
Signals - EQUISAT (Fixed-Time/SCATS) Isolated Cycle Time = 125 seconds (Site User-Given Cycle Time)

Vehicle	e Mover	nent Perf	ormance					_							
Mov ID	Turn	Mov Class	Demand [ Total		Arrival I [ Total	Flows HV]	Deg. Satn	Aver. Delay	Level of Service	95% Back [ Veh.	Of Queue Dist]	Prop. Que	Eff. Stop Rate	Aver. No. of Cycles	Aver. Speed
			veh/h	%	veh/h	%	v/c	sec		veh	m				km/h
South: I	East Pde														
1	L2	All MCs	315	0.0	315	0.0	0.298	20.4	LOSC	9.8	72.0	0.56	0.73	0.56	39.4
2	T1	All MCs	783	0.6	783	0.6	0.711	20.7	LOS C	34.1	251.9	0.79	0.72	0.79	44.9
3	R2	All MCs	1373	1.3	1373	1.3	* 1.065	100.2	LOS F	56.1	418.4	1.00	1.18	1.43	22.5
Approa	ch		2471	0.9	2471	0.9	1.065	64.9	LOSE	56.1	418.4	0.88	0.97	1.11	28.3
East: G	uilford R	d													
4	L2	All MCs	601	1.3	601	1.3	0.283	11.8	LOS B	7.7	57.4	0.35	0.66	0.35	48.7
5	T1	All MCs	742	1.8	742	1.8	0.577	36.6	LOS D	18.6	139.2	0.88	0.76	0.88	32.6
Approa	ch		1343	1.6	1343	1.6	0.577	25.5	LOS C	18.6	139.2	0.65	0.72	0.65	39.6
North: \	Whatley (	Cres													
8	T1	All MCs	863	1.6	863	1.6	*1.033	85.6	LOS F	26.3	197.2	1.00	1.10	1.33	25.1
Approa	ch		863	1.6	863	1.6	1.033	85.6	LOSF	26.3	197.2	1.00	1.10	1.33	25.1
West: 0	Builford R	ld.													
10	L2	All MCs	103	0.0	103	0.0	1.058	99.4	LOSF	54.6	409.5	1.00	1.27	1.41	18.7
11	T1	All MCs	1248	2.3	1248	2.3	<b>*</b> 1.058	92.8	LOS F	55.0	413.5	1.00	1.28	1.41	19.1
Approa	ch		1352	2.1	1352	2.1	1.058	93.3	LOSF	55.0	413.5	1.00	1.28	1.41	19.1
All Vehi	cles		6028	1.4	6028	1.4	1.065	65.4	LOSE	56.1	418.4	0.87	1.00	1.11	27.0

Document No: D24#151441 Page 11 of 14

#### 6 COMMENTARY

The intersections have been assessed based on the Degree of Saturation (DOS), Level of Service (LOS) and critical queue length.

The DOS is a measure of the capacity of an intersection and a DOS greater than 100% indicates the intersection is over capacity. The desired DOS for various intersections are:

• Signalised intersections: 90%

• Roundabouts: 85%

• Stop/Give-Way Control: 80%

The LOS indicates the average delay that a vehicle will experience at an intersection. There are six LOS grades ranging from A (Good) to F (Poor). Table 2 shows the average delay (d) in seconds for each grade. Generally, the desired LOS is '**D**' or better.

Table 2: Level of Service Definitions based on Delay only (for Vehicles).

Level of	Con	Control delay per vehicle in seconds (d)											
Service	Signals	Roundabouts	Sign Control										
Α	d ≤ 10	d ≤ 10	d ≤ 10										
В	10 < d ≤ 20	10 < d ≤ 20	10 < d ≤ 15										
С	20 < d ≤ 35	20 < d ≤ 35	15 < d ≤ 25										
D	35 < d ≤ <b>55</b>	35 < d ≤ <b>50</b>	25 < d ≤ <b>35</b>										
E	<b>55</b> < d ≤ 80	<b>50</b> < d ≤ 70	<b>35</b> < d ≤ 50										
F	b > 08	70 < d	50 < d										

The critical queue length indicates the extent of the backlog (in metres) caused by delayed vehicles. It helps assess whether the queued traffic in a turning pocket will encroach into the through lane.

Document No: D24#151441 Page 12 of 14

For the requested scenarios, the following comments are of note:

Scenario	Peak	Comments
Existing Layout 2021	AM & PM	The results of the analysis indicate that the Guildford Road to East Parade left turn movement is operating at capacity in the AM peak with a DOS just above 100% and LOS of 'F'.  The 95 <sup>th</sup> percentile queues of the left turn movement are expected to extend beyond the pocket length of 145m to 470m in the AM peak. The vehicles that are unable to be contained in the pocket will pose a safety risk because of the higher likelihood of being involved in a rear-ended crash with the through movement vehicles.
Existing Layout 2026	AM & PM	The results of the analysis indicate that the Guildford Road to East Parade left turn movement will operate poorly in the AM peak with a DOS above 100% and LOS of 'F'.  The 95 <sup>th</sup> percentile queues of the left turn movement are expected to extend beyond the pocket length of 145m to beyond 600m in the AM peak. The vehicles that are unable to be contained in the pocket will pose a safety risk because of the higher likelihood of being involved in a rear-ended crash with the through movement vehicles.
Option 2a 2031 and 2036	AM & PM	The results of the analysis indicate that the Guildford Road to East Parade left turn movement will operate satisfactorily with the dual left turn pockets with a DOS below 90% and worst LOS of 'D' in 2036 despite the 4.5% increase in traffic volumes.  The length of auxiliary lanes is usually selected based on the maximum of the length of the 95 <sup>th</sup> percentile queue or the length of lane required for a design vehicle to decelerate at 2.5m/s² to a stop condition. For Guildford Road with a speed limit of 60km/h, the length of lane required to decelerate to a stop condition is 75m. The 95 <sup>th</sup> percentile queues of the left turn movement is expected to extend to beyond the

Document No: D24#151441 Page 13 of 14

proposed pocket length in both the 2031 and 2036 AM scenarios.

Therefore, the current proposed left turn pocket length will be required for storage of turning movements expected by 2031 and beyond. Also, considering the through traffic queue extends over 500m, the longer pocket length would be necessary to ensure left-turning vehicles are not held up in the through queue and thus worsening the degree of saturation of the intersection.

----- END OF REPORT -----

Document No: D24#151441 Page 14 of 14